Approved CR

IAA Fremont
6700 Stevenson Blvd
Branch No 334
Fremont, CA 94538
(510) 668-1665/(510) 668-0106
WHOLESALE ASSESSMENT ONLY



Make/Model:	**2019 JEEP CHEROKEE**
Bodystyle/Series:	**Sport Utility Vehicle LATITUDE 4X4**
Color:	**Silver**
Mileage:	**52,456 (Verified)**
Turn-in Mileage:	-
VIN:	**1C4PJMCB6KD440350**
Work Order/ Stock Number:	**46493052**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G61-1150W**
Vehicle Grade :	**Grade 2.1**
Remarks:	-
Announcements:	• JUNK TITLE • PARTS ONLY • NOT TO BE TITLED FOR HWY USE
Certification :	-
Req. Prev. Repair Order:	-

Drivable: Yes

Equipment

Transmission:	**Automatic Transmission**	A/C:	**No**
Engine:	**4-Cylinder Gas**	Cruise Control:	**Yes**
Engine Size:	**2.4 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**Yes**
Radio:	-	Pwr Windows	**Yes**
Interior - Type/Color:	**Cloth Interior /BLACK**	Rear Defroster:	**Yes**
Airbag:	**Driver Side Air Bag**	Tilt Steering:	**Yes**


Equipment

Seats:	**Buckets**	Drive Type:	**4-Wheel Drive**
Seat Count:	-	Brakes:	**Anti Lock Brakes**

Additional Equipment:

Car Tire Size - LF 225 / 65 R 17	Car Tire Size - LR 225 / 65 R 17	Car Tire Size - RR 225 / 65 R 17
Car Tire Size - RF 225 / 65 R 17	LF Tires - 5/32 inch	LR Tires - 8/32 inch
RF Tires - 5/32 inch	RR Tires - 9/32 inch	Tire Brand - Front Left - FIRESTONE
Tire Brand - Front Right - FIRESTONE	Tire Brand - Rear Left - FIRESTONE	Tire Brand - Rear Right - FIRESTONE
Tire Model - LF - Destination LE2	Tire Model - RF - Destination LE2	Tire Model - RR - Destination LE2
Tire Model - LR - Destination LE2		


Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 4	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Side Panel	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-
	Warning Light - Engine	On	-	Unacceptable
	Rear Seats	Photo Only	-	-
	Odometer	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Left Front Fender	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 6	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Instrument Panel	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Front Bumper Reinforcement	Bent	-	> 12 Inches
	Front Bumper	Missing	-	Replacement Required
	Left Head Lamp	Missing	-	Replacement Required

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Head Lamp	Missing	-	Replacement Required
	Hood	Dent(S) W/ Paint Dmg	-	> 12 Inches
	Rear Bumper	Broken	-	Replacement Required
	Hood Latch	Broken	-	Replacement Required
	Rf Mirror Cover	Chipped	-	1
	Right Rear Door	Dent(S) W/ Paint Dmg	-	< 1/8 Inch

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Front Door	Chipped	-	10 Or More
	Left Front Moulding	Misaligned	-	Repair Required
	Hood Molding	Broken	-	Replacement Required

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.