



Approved
CR

IAA Providence
160 Amaral St
Branch No 644
Riverside, RI 02915
(401) 438-5254/(401) 438-3523
WHOLESALE ASSESSMENT ONLY

Make/Model: **2018 CHEVROLET
EXPRESS 3500**

Bodystyle/Series: **- WORK VAN**

Color: **Silver**

Mileage: **26,350 (Verified)**

Turn-in Mileage: **-**

VIN: **1GCZGHFP0J1335230**

Work Order/
Stock Number: **46362662**

Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**

Client Stock #: **G433859V**

Vehicle Grade : **Grade 2.2**

Remarks: **-**

Announcements:

- ANNOUNCEMENTS:
- Warning indicator on
- repairs may be needed
- please check OBDII
- report on IAA site.

Certification : **-**

Req. Prev. Repair **-**

Order: **-**



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	6-Cylinder Gas	Cruise Control:	Yes
Engine Size:	4.3 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /GRAY	Rear Defroster:	No
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Buckets	Drive Type:	Rear Wheel Drive
Seat Count:	-	Brakes:	Disc

Equipment

Additional Equipment:

Car Tire Size - LF 245 / 75 R 16

Car Tire Size - LR 245 / 75 R 16

Car Tire Size - RR 245 / 75 R 16

Car Tire Size - RF 245 / 75 R 16

LF Tires - 6/32 inch

LR Tires - 6/32 inch

RF Tires - 6/32 inch

RR Tires - 6/32 inch

Tire Brand - Front Left - SAILUN

Tire Brand - Front Right - sail

Tire Brand - Rear Left - sail

Tire Brand - Rear Right - sail


Tire Model - RR - Terramax H/T

Tire Model - RF - Terramax H/T



Tire Model - LR - Terramax H/T

Tire Model - LF - Terramax H/T

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Front Fender	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Warning Light - Engine	On	-	Unacceptable

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Front Fender	Dent(S) W/ Paint Dmg	-	> 12 Inches
	Right Front Fender	Dent(S) W/ Paint Dmg	-	< 1/8 Inch
	Right Rear Cargo Door	Heavy Scratch	-	1/8 To 1/2 Inch
	Rear Metal Bumper Painted	Multiple Dents/Paint Damage	-	2
	Left Side Panel	Heavy Scratch	-	> 12 Inches
	Steering Wheel	Worn	-	Replacement Required

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Front Door	Dent(S) W/ Paint Dmg	-	> 12 Inches
	Left Rocker Panel	Multiple Dents/Paint Damage	-	2
	Left Front Moulding	Broken	-	Replacement Required

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.