



Approved CR

IAA Birmingham
1600 Highway 150
Branch No 727
Bessemer, AL 35022
(205) 426-2300/(205) 428-5332
WHOLESALE ASSESSMENT ONLY

Make/Model: **2024
CHEVROLET
EQUINOX**
Bodystyle/Series: **Sport Utility
Vehicle FWD
LS**
Color: **Black**
Mileage: **67,074
(Verified)**
Turn-in Mileage: **-**
VIN: **3GNAXHEG6RL195453**
Work Order/
Stock Number: **46077366**
Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**
Client Stock #: **G421180Z**
Vehicle Grade : **Grade 0.8**
Remarks: **-**
Announcements: **• Salvage**
Certification : **-**
Req. Prev. Repair **-**
Order: **-**



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	4-Cylinder Gas	Cruise Control:	Yes
Engine Size:	1.5 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /BLACK	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Buckets	Drive Type:	Front Wheel Drive
Seat Count:	-	Brakes:	Anti Lock Brakes

Equipment

Additional Equipment:

Car Tire Size - LF 225 / 65 R 17

Car Tire Size - LR 225 / 65 R 17

Car Tire Size - RR 225 / 65 R 17

Car Tire Size - RF 225 / 65 R 17

LF Tires - 4/32 inch

LR Tires - 7/32 inch

RF Tires - 4/32 inch

RR Tires - 6/32 inch

Tire Brand - Front Left - MICHELIN

Tire Brand - Front Right - MICHELIN

Tire Brand - Rear Left - MICHELIN

Tire Brand - Rear Right - MICHELIN

Tire Model - RR - Primacy A/S

Tire Model - RF - Primacy A/S

Tire Model - LR - Primacy A/S

Tire Model - LF - Primacy A/S

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right D Pillar	Broken	-	Replacement Required
	Warning - Esc	On	-	Unacceptable
	Warning Light - Air Bag	On	-	Unacceptable
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-

Non Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Rear Seats	Photo Only	-	-
	Right Inner Qtr Panel	Broken	-	Replacement Required
	Right Rear Wheel Housing	Broken	-	Replacement Required
	Rear Body Panel Structure	Broken	-	Replacement Required
	Warning Light - Abs	On	-	Unacceptable
	Warning - Traction Control	On	-	Unacceptable
	Warning Light - Brakes	On	-	Unacceptable

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Warning Light - Engine	On	-	Unacceptable
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rr Axle Assembly	Broken	-	Replacement Required
	Windshield	Cracked	-	> 12 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Front Bumper	Chipped	-	3
	Hood	Chipped	-	3
	Right Front Door Cladding	Loose	-	Repair Required
	Right Rear Door Cladding	Loose	-	Repair Required
	Right Rear Door	Dent(S) W/ Paint Dmg	-	> 12 Inches
	Right Qtr Panel	Severe Damage	-	Replacement Required

Chargeable Damages

Photo	Item	Damage	Action	Severity
	R Bumper Textured	Broken	-	Replacement Required
	Rear Bumper Cover Upper	Broken	-	Replacement Required
	Right Tail Light	Broken	-	Replacement Required
	Right Brake Light	Broken	-	Replacement Required
	Lift Gate	Dent(S) W/ Paint Dmg	-	> 12 Inches

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.