



Approved CR

IAA Tidewater
211 Production Drive
Branch No 725
Yorktown, VA 23693
(757) 595-8493/(757) 595-8691
WHOLESALE ASSESSMENT ONLY

Make/Model: **2019
CHEVROLET
EXPRESS
3500**

Bodystyle/Series: **- LS**

Color: **White**

Mileage: **97,837
(Verified)**

Turn-in Mileage: **-**

VIN: **1GAZGNFG4K1353044**

Work Order/
Stock Number: **46251393**

Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**

Client Stock #: **G431421W**

Vehicle Grade : **Grade 0.7**

Remarks: **-**

Announcements: **• Announcement:
Salvage Title**

Certification : **-**

Req. Prev. Repair **-**

Order: **-**



Drivable: No

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	8-Cylinder Flex Fuel	Cruise Control:	Yes
Engine Size:	6 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Vinyl Interior /GRAY	Rear Defroster:	Yes
Airbag:	-	Tilt Steering:	Yes
Seats:	5th	Drive Type:	Rear Wheel Drive
Seat Count:	-	Brakes:	Power Brakes

Equipment

Additional Equipment:

Car Tire Size - LR 245 / 75 R 16	Car Tire Size - RF 245 / 75 R 16	Car Tire Size - RR 245 / 75 R 16
Car Tire Size - LF 245 / 75 R 16	LF Tires - 12/32 inch	LR Tires - 6/32 inch
RF Tires - 11/32 inch	RR Tires - 4/32 inch	Tire Brand - Front Left - STARFIRE
Tire Brand - Front Right - STARFIRE	Tire Brand - Rear Left - SUREDRIVE	Tire Brand - Rear Right - SUREDRIVE
Tire Model - RR - highway	Tire Model - RF - Solarus HT	Tire Model - LR - highway
Tire Model - LF - Solarus HT		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-

Non Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-
	Extra Photo 6	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	4th Row Seat	Broken	-	Replacement Required
	Left Head Lamp	Missing	-	Replacement Required
	Left Front Fender	Severe Damage	-	Replacement Required
	Front Metal Bumper Painted	Broken	-	Replacement Required
	Grille	Broken	-	Replacement Required

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Head Lamp	Missing	-	Replacement Required
	Right Front Door	Heavy Scratch	-	> 12 Inches
	Right Rear Door Glass	Broken	-	Replacement Required
	Right Qtr Panel	Dent(S) W/ Paint Dmg	-	> 12 Inches
	Left Rear Cargo Door	Dent(S) W/ Paint Dmg	-	3 To 4 Inches
	Left Qtr Panel	Dent(S) W/ Paint Dmg	-	> 12 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Airbag - Front Left	Deployed	-	Replacement Required
	Airbag - Front Right	Deployed	-	Replacement Required
	Right Rear Seat	Torn	-	1 To 2 Inches

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.