



Approved CR

IAA Knoxville
3634 E. Governor John Sevier Hwy
Branch No 754
Knoxville, TN 37914
(865) 525-7349/(865) 522-8813
WHOLESALE ASSESSMENT ONLY

Make/Model: **2025 NISSAN
ALTIMA**
Bodystyle/Series: **4 Door Sedan
S FWD**
Color: **Gray**
Mileage: **13,113
(Verified)**
Turn-in Mileage: **-**
VIN: **1N4BL4BV9SN412509**
Work Order/
Stock Number: **46296844**
Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**
Client Stock #: **G10C3224**
Vehicle Grade : **Grade 0.8**
Remarks: **-**
Announcements: **-**
Certification : **-**
Req. Prev. Repair **-**
Order:



Drivable: Yes

Equipment

Transmission:	Continuously Variable Transmission	A/C:	No
Engine:	4-Cylinder Gas	Cruise Control:	Yes
Engine Size:	2.5 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /BLACK	Rear Defroster:	Yes
Airbag:	-	Tilt Steering:	Yes
Seats:	Buckets	Drive Type:	Front Wheel Drive
Seat Count:	-	Brakes:	Anti Lock Brakes

Equipment

Additional Equipment:

Car Tire Size - RF 215 / 60 R 16

Car Tire Size - RR 215 / 60 R 16

Car Tire Size - LR 215 / 60 R 16

Car Tire Size - LF 215 / 60 R 16

LF Tires - 5/32 inch

LR Tires - 5/32 inch

RF Tires - 5/32 inch

RR Tires - 5/32 inch

Tire Brand - Front Left - HANKOOK

Tire Brand - Front Right - HANKOOK

Tire Brand - Rear Left - HANKOOK

Tire Brand - Rear Right - HANKOOK

Tire Model - RR - Kinergy GT H436

Tire Model - RF - Kinergy GT H436

Tire Model - LR - Kinergy GT H436

Tire Model - LF - Kinergy GT H436

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 4	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Warning - Collision Avoidance	On	-	Unacceptable
	Warning - Rear Parking Aid	On	-	Unacceptable
	Right Apron	Kinked	-	1 To 2 Inches
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Core Support	Kinked	-	1 To 2 Inches
	Right Front Rail	Kinked	-	1 To 2 Inches
	Warning Light - Engine	On	-	Unacceptable

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Warning - Traction Control	On	-	Unacceptable
	Warning Light - Air Bag	On	-	Unacceptable

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Windshield	Broken	-	Replacement Required
	Hood	Severe Damage	-	Replacement Required
	Radiator	Cracked	-	Replacement Required
	Grille	Missing	-	Replacement Required

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Front Bumper	Missing	-	Replacement Required
	Left Head Lamp	Missing	-	Replacement Required
	Right Head Lamp	Broken	-	Replacement Required
	Right Front Fender	Dent(S) W/ Paint Dmg	-	> 12 Inches
	Right Side Curtain Air Bag	Deployed	-	Replacement Required
	Right Knee Airbag	Deployed	-	Replacement Required

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Airbag - Front Left	Deployed	-	Replacement Required
	Left Knee Airbag	Deployed	-	Replacement Required
	Airbag - Front Right	Deployed	-	Replacement Required

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.