



Approved
CR

IAA Buffalo
366 Vulcan Street
Branch No 624
Buffalo, NY 14204
(716) 874-9890/(716) 874-9605
WHOLESALE ASSESSMENT ONLY

Make/Model: **2021 NISSAN
ALTIMA**
Bodystyle/Series: **4 Door Sedan S FWD**
Color: **Black**
Mileage: **50,104 (Verified)**
Turn-in Mileage: **-**
VIN: **1N4BL4BV9MN347020**
Work Order/
Stock Number: **46379309**
Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalessupport@gsa.gov**
Client Stock #: **G102683X**
Vehicle Grade : **Grade 4.1**
Remarks: **-**
Announcements: **• ANNOUNCEMENTS:**
Certification : **-**
Req. Prev. Repair **-**
Order:



Drivable: Yes

Equipment

Transmission:	Continuously Variable Transmission	A/C:	No
Engine:	4-Cylinder Gas	Cruise Control:	Yes
Engine Size:	2.5 L	Pwr Steering:	Yes
Roof:	Carriage	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /BLACK	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	3rd	Drive Type:	Front Wheel Drive
Seat Count:	-	Brakes:	Anti Lock Brakes

Equipment

Additional Equipment:

Car Tire Size - LR 215 / 60 R 16

Car Tire Size - RR 215 / 60 R 16

Car Tire Size - RF 215 / 60 R 16

Car Tire Size - LF 215 / 60 R 16

LF Tires - 5/32 inch

LR Tires - 5/32 inch

RF Tires - 5/32 inch

RR Tires - 5/32 inch

Tire Brand - Front Left - HANKOOK

Tire Brand - Front Right - HANKOOK

Tire Brand - Rear Left - HANKOOK

Tire Brand - Rear Right - HANKOOK

Tire Model - LF - Kinergy PT H737

Tire Model - LR - Kinergy PT H737

Tire Model - RF - Kinergy PT H737

Tire Model - RR - Kinergy PT H737

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Instrument Panel	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Keys	Photo Only	-	-
	Odometer	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Photo - Dash	Photo Only	-	-

Non Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Right Rear Bumper/Cover	Photo Only	-	-
	Engine	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Left Side Panel	Photo Only	-	-

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Left Front Wheel Cover	Curb Rash	-	4 To 5 Inches

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Front Bumper	Misaligned	-	Repair Required
	Right Rear Wheel Cover	Curb Rash	-	3 To 4 Inches
	Right Front Wheel Cover	Curb Rash	-	4 To 5 Inches
	Left Rear Door	Heavy Scratch	-	1/2 To 1 Inch

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.