



Original CR

IAA Fontana
9951 Banana Ave
Branch No 132
Fontana, CA 92335
(909)355-9400/(909)822-9311
WHOLESALE ASSESSMENT ONLY

Make/Model: **2021 HYUNDAI
IONIQ HYBRID**
Bodystyle/Series: **4 Door Hatch
Back BLUE**
Color: **Silver**
Mileage: **34,156 (Verified)**
Turn-in Mileage: **-**
VIN: **KMHC65LC1MU247469**
Work Order/
Stock Number: **46161516**
Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**
Client Stock #: **G133316Y**
Vehicle Grade : **Grade 2.2**
Remarks: **-**



Announcements:

• CONDITION
UNKNOWN
• REPAIRS OR
REPLACEMENT
MAY BE
NEEDED
• SALVAGE
STAMPED
CERTIFICATE
TO OBTAIN
TITLE WILL BE
ISSUED
• TOWED OUT
• TOWED IN
• PARTS MAY BE
MISSING

Certification : **-**
Req. Prev. Repair **-**
Order: **-**

Drivable: Yes

Equipment

Transmission:	-	A/C:	No
Engine:	4-Cylinder Hybrid	Cruise Control:	No

Equipment

Engine Size:	1.6 L	Pwr Steering:	No
Roof:	-	Pwr Locks:	No
Radio:	-	Pwr Windows	No
Interior - Type/Color:	- / -	Rear Defroster:	No
Airbag:	Driver Side Air Bag	Tilt Steering:	No
Seats:	-	Drive Type:	Front Wheel Drive
Seat Count:	-	Brakes:	-

Additional Equipment:

Car Tire Size - RR 195 / 65 R 15	Car Tire Size - RF 195 / 65 R 15	Car Tire Size - LF 195 / 65 R 15
Car Tire Size - LR 195 / 65 R 15	LF Tires - 3/32 inch	LR Tires - 6/32 inch
RF Tires - 5/32 inch	RR Tires - 7/32 inch	Tire Brand - Front Left - HANKOOK
Tire Brand - Front Right - HANKOOK	Tire Brand - Rear Left - HANKOOK	Tire Brand - Rear Right - HANKOOK
Tire Model - LF - Kinergy GT H436	Tire Model - LR - Kinergy GT H436	Tire Model - RF - Kinergy GT H436
Tire Model - RR - Kinergy GT H436		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Core Support	Broken	-	Replacement Required
	Warning - Tire Pressure	On	-	Unacceptable
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Grille	Broken	-	Replacement Required
	Front Bumper	Broken	-	Replacement Required
	Hood	Dent(S) W/ Paint Dmg	-	> 12 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Head Lamp	Broken	-	Replacement Required
	Spoiler	Peeling	-	> 12 Inches
	Rear Bumper	Multiple Scratches Heavy	-	2
	Left Front Tire	Worn	-	Replacement Required
	Windshield	Broken	-	Replacement Required

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.