



Approved CR

IAA Raleigh
60 Sadisco Road
Branch No 747
Clayton, NC 27520
(919) 553-6148/(919) 553-2857
WHOLESALE ASSESSMENT ONLY

Make/Model: **2021
HYUNDAI
SONATA**

Bodystyle/Series: **4 Door Sedan
BLUE**

Color: **Black**

Mileage: **64,148
(Verified)**

Turn-in Mileage: **-**

VIN: **KMHL24JJ0MA028205**

Work Order/
Stock Number: **45720648**

Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**

Client Stock #: **G100278Y**

Vehicle Grade : **Grade 1.2**

Remarks: **-**

Announcements: **• Salvage**

Certification : **-**

Req. Prev. Repair **-**

Order: **-**



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	4-Cylinder Hybrid	Cruise Control:	Yes
Engine Size:	2 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /-	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Bench	Drive Type:	Front Wheel Drive
Seat Count:	-	Brakes:	Disc

Equipment

Additional Equipment:

Car Tire Size - LF 205 / 65 R 16

Car Tire Size - LR 205 / 65 R 16

Car Tire Size - RR 205 / 65 R 16

Car Tire Size - RF 205 / 65 R 16

LF Tires - 8/32 inch

LR Tires - 9/32 inch

RF Tires - 8/32 inch

RR Tires - 7/32 inch

Tire Brand - Front Left - vantage

Tire Brand - Front Right - vantage

Tire Brand - Rear Left - vantage

Tire Brand - Rear Right - vantage

Tire Model - RR - touring a/s

Tire Model - RF - touring a/s

Tire Model - LR - touring a/s

Tire Model - LF - touring a/s

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Apron	Kinked	-	> 12 Inches
	Core Support	Kinked	-	> 12 Inches
	Rear Seats	Photo Only	-	-
	Odometer	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Photo - Dash	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Rear Bumper/Cover	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Front Wheel	Curb Rash	-	5 To 6 Inches
	Right Rear Seat Cushion	Stained	-	Permanent
	Left Rear Seat Cushion	Stained	-	Permanent

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Windshield	Cracked	-	> 12 Inches
	Radiator	Broken	-	Replacement Required
	A/C Condensor	Broken	-	Replacement Required
	Hood	Severe Damage	-	Replacement Required
	Grille	Broken	-	Replacement Required
	Left Head Lamp	Broken	-	Replacement Required

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Front Bumper	Broken	-	Replacement Required

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.