



Approved CR

IAA Minneapolis/St. Paul
1280 Jackson Street
Branch No 526
St. Paul, MN 55117
(651) 488-0581/(651) 488-3644
WHOLESALE ASSESSMENT ONLY

Make/Model: **2019 FORD
F-250**
Bodystyle/Series: **Crew Cab XL**
Color: **Blue**
Mileage: **82,092
(Verified)**
Turn-in Mileage: **-**
VIN: **1FT7W2B68KEE37700**
Work Order/
Stock Number: **46384582**
Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**
Client Stock #: **G63B3280**
Vehicle Grade : **Grade 2.9**
Remarks: **-**
Announcements: **-**
Certification : **-**
Req. Prev. Repair **-**
Order: **-**



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	8-Cylinder Gas	Cruise Control:	Yes
Engine Size:	6.2 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /GRAY	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Buckets	Drive Type:	4-Wheel Drive
Seat Count:	-	Brakes:	Disc

Equipment

Additional Equipment:

Car Tire Size - RR 245 / 75 R 17

Car Tire Size - RF 245 / 75 R 17

Car Tire Size - LF 245 / 75 R 17

Car Tire Size - LR 245 / 75 R 17

LF Tires - 2/32 inch

LR Tires - 2/32 inch

RF Tires - 3/32 inch

RR Tires - 3/32 inch

Tire Brand - Front Left - NEXEN

Tire Brand - Front Right - NEXEN

Tire Brand - Rear Left - NEXEN

Tire Brand - Rear Right - NEXEN

Tire Model - LF - Roadian Atx

Tire Model - LR - Roadian Atx

Tire Model - RF - Roadian Atx

Tire Model - RR - Roadian Atx

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Seats	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Instrument Panel	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Side Panel	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Keys	Photo Only	-	-
	Engine	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Odometer	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Photo - Dash	Photo Only	-	-

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Left Rear Wheel	Curb Rash	-	9 To 10 Inches
	Left Bed Side	Chipped	-	4
	Tailgate	Chipped	-	2
	Right Front Fender	Chipped	-	2
	Right Front Wheel	Corrosion	-	5 To 6 Inches
	Right Rear Wheel	Corrosion	-	3 To 4 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Rear Tire	Worn	-	Replacement Required
	Right Bed Side	Dent(S) W/ Paint Dmg	-	> 12 Inches
	Left Front Tire	Worn	-	Replacement Required
	Left Front Wheel	Corrosion	-	3 To 4 Inches
	Front Metal Bumper Chrome	Dent(S) W/No Paint Dmg	-	3 To 4 Inches
	Left Rear Tire	Worn	-	Replacement Required

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Right Front Tire	Worn	-	Replacement Required

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.