



Approved CR

IAA Macon
2200 Trade Ave.
Branch No 734
Macon, GA 31217
(478) 314-0031/(478) 314-0040
WHOLESALE ASSESSMENT ONLY

Make/Model: **2016
CHEVROLET
SILVERADO
3500HD**

Bodystyle/Series: **Crew Cab
WT**

Color: **Red**

Mileage: **74,607
(Verified)**

Turn-in Mileage: **-**

VIN: **1GC4KYCGXGF187869**

Work Order/
Stock Number: **46324871**

Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalessupport@gsa.gov**

Client Stock #: **G631129S**

Vehicle Grade : **Grade 2.1**

Remarks: **-**

Announcements: **-**

Certification : **-**

Req. Prev. Repair **-**

Order: **-**



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	8-Cylinder Flex Fuel	Cruise Control:	Yes
Engine Size:	6 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth/Vinyl /GRAY	Rear Defroster:	No
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Bench	Drive Type:	4-Wheel Drive
Seat Count:	-	Brakes:	Anti Lock Brakes

Equipment

Additional Equipment:

Car Tire Size - RR 265 / 70 R 18

Car Tire Size - RF 265 / 70 R 18

Car Tire Size - LF 265 / 70 R 18

Car Tire Size - LR 265 / 70 R 18

LF Tires - 9/32 inch

LR Tires - 10/32 inch

RF Tires - 9/32 inch

RR Tires - 10/32 inch

Tire Brand - Front Left - FIRESTONE

Tire Brand - Front Right - FIRESTONE

Tire Brand - Rear Left - FIRESTONE

Tire Brand - Rear Right - FIRESTONE

Tire Model - LF - Transforce A/T2

Tire Model - LR - Transforce A/T2

Tire Model - RF - Transforce A/T2

Tire Model - RR - Transforce A/T2

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-
	Extra Photo 6	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Bed Side	Multiple Scratches Heavy	-	10 Or More
	Rear Metal Bumper Chrome	Dent(S) W/No Paint Dmg	-	9 To 10 Inches
	Right Tail Light	Cracked	-	Replacement Required
	Left Rear Bumper Step Pad	Broken	-	Replacement Required
	Inside Bed	Multiple Dents/Paint Damage	-	10 Or More

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Tailgate	Dent(S) W/ Paint Dmg	-	1/8 To 1/2 Inch
	Left Bed Side	Heavy Scratch	-	1/8 To 1/2 Inch
	Left Front Seat Cushion	Stained	-	Permanent
	Left Rear Door	Peeling	-	> 12 Inches
	Tailgate Molding	Missing	-	Replacement Required
	Hood	Dent(S) W/ Paint Dmg	-	9 To 10 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Front Metal Bumper Chrome	Heavy Scratch	-	< 1/8 Inch
	Right Front Door	Dent(S) W/ Paint Dmg	-	2 To 3 Inches
	Right Rear Door	Dent(S) W/ Paint Dmg	-	1/8 To 1/2 Inch

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.