



Approved
CR

IAA Manchester
75 Lowell Road
Branch No 643
Salem, NH 03079
(603) 893-2300/(603) 898-3870
WHOLESALE ASSESSMENT ONLY

Make/Model: **2024 SUBARU CROSSTREK**
Bodystyle/Series: **Sport Utility Vehicle SPORT**
Color: **Blue**
Mileage: **61,936 (Verified)**
Turn-in Mileage: **-**
VIN: **4S4GUHF66R3775813**
Work Order/ Stock Number: **46362381**
Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**
Client Stock #: **G61A2180**
Vehicle Grade : **Grade 0.5**
Remarks: **-**
Announcements:

• ANNOUNCEMENTS:
Salvage Title

Certification : **-**
Req. Prev. Repair **-**
Order:



Drivable: No

Equipment

Transmission:	Continuously Variable Transmission	A/C:	Yes
Engine:	4-Cylinder Gas	Cruise Control:	Yes
Engine Size:	2.5 L	Pwr Steering:	Yes
Roof:	-	Pwr Locks:	Yes
Radio:	AM Radio	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /GRAY	Rear Defroster:	Yes
Airbag:	-	Tilt Steering:	No
Seats:	Bench	Drive Type:	All Wheel Drive
Seat Count:	-	Brakes:	Anti Lock Brakes

Equipment

Additional Equipment:

Car Tire Size - LF 215 / 55 R 18	Car Tire Size - LR 215 / 55 R 18	Car Tire Size - RR 215 / 55 R 18
Car Tire Size - RF 215 / 55 R 18	LF Tires - 10/32 inch	LR Tires - 9/32 inch
RF Tires - 11/32 inch	RR Tires - 11/32 inch	Tire Brand - Front Left - NORDMAN
Tire Brand - Front Right - NORDMAN	Tire Brand - Rear Left - NORDMAN	Tire Brand - Rear Right - NORDMAN
Tire Model - RR - North 9	Tire Model - RF - North 9	Tire Model - LR - North 9
Tire Model - LF - North 9		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-
	Extra Photo 6	Photo Only	-	-
	Extra Photo 7	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Hood	Severe Damage	-	Replacement Required
	Front Bumper	Scraped	-	3 To 4 Inches
	Left Front Fender	Severe Damage	-	Replacement Required
	Left Front Wheel	Curb Rash	-	> 12 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Front Door	Severe Damage	-	Replacement Required
	Left Rear Door	Severe Damage	-	Replacement Required
	Left Side Curtain Air Bag	Deployed	-	Replacement Required
	Left Qtr Panel	Severe Damage	-	Replacement Required
	Left Rear Wheel	Curb Rash	-	> 12 Inches
	Windshield	Broken	-	Replacement Required

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Front Door	Severe Damage	-	Replacement Required
	Right Front Wheel	Broken	-	Replacement Required
	Right Front Tire	Flat	-	Repair Required
	Front Bumper	Broken	-	Replacement Required
	Right Side Curtain Air Bag	Deployed	-	Replacement Required
	Right Rear Wheel	Curb Rash	-	> 12 Inches

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Left Drip Rail	Severe Damage	-	Replacement Required
	Roof Panel	Severe Damage	-	Replacement Required

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.