



Approved
CR

IAA Portland
4415 NE 158th Avenue
Branch No 308
Portland, OR 97230
(503) 253-1500/(503) 253-9359
WHOLESALE ASSESSMENT ONLY

2017
Make/Model: **CHEVROLET
SILVERADO
1500**
Bodystyle/Series: **- WT**
Color: **White**
Mileage: **23,331 (Verified)**
Turn-in Mileage: **-**
VIN: **1GCVKNEH4HZ361959**
Work Order/
Stock Number: **46273033**
Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**
Client Stock #: **G623020U**
Vehicle Grade : **Grade 3.5**
Remarks: **-**
Announcements:

- PARTS MAY BE MISSING
- WINCH CONDITION UNKNOWN
- REPAIRS OR REPLACEMENT MAY BE NEEDED

Certification : **-**
Req. Prev. Repair **-**
Order: **-**



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	6-Cylinder Gas	Cruise Control:	Yes
Engine Size:	4.3 L	Pwr Steering:	Yes
Roof:	Coach	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /GRAY	Rear Defroster:	Yes


Equipment

Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	5th	Drive Type:	4-Wheel Drive
Seat Count:	-	Brakes:	Disc
Additional Equipment:			
Car Tire Size - LF 265 / 70 R 17	Car Tire Size - LR 265 / 70 R 17	Car Tire Size - RF 265 / 70 R 17	
Car Tire Size - RR 265 / 70 R 17	LF Tires - 14/32 inch	LR Tires - 13/32 inch	
RF Tires - 14/32 inch	RR Tires - 13/32 inch	Tire Brand - Front Left - SUMITOMO	
Tire Brand - Front Right - SUMITOMO	Tire Brand - Rear Left - SUMITOMO	Tire Brand - Rear Right - SUMITOMO	
Tire Model - LF - HTR Enhance LX2	Tire Model - LR - HTR Enhance LX2	Tire Model - RF - HTR Enhance LX2	
Tire Model - RR - HTR Enhance LX2			

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Keys	Photo Only	-	-
	Engine	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Warning Light - Engine	On	-	Unacceptable
	Front Bumper Extension	Aftermarket	-	Acceptable
	Aftermarket Accessory	Aftermarket	-	Acceptable

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Rear Door	Dent(S) W/No Paint Dmg	-	1 To 2 Inches
	Right Drip Rail	Light Scratch	-	1/2 To 1 Inch
	Left Front Wheel	Curb Rash	-	1/2 To 1 Inch

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Bed Side	Dent(S) W/ Paint Dmg	-	1/2 To 1 Inch
	Rear Metal Bumper Painted	Chipped	-	3
	Right Front Door	Heavy Scratch	-	1/2 To 1 Inch
	Right Rocker Panel	Multiple Scratches Heavy	-	3
	Right Front Center Cap	Missing	-	Replacement Required
	Front Metal Bumper Painted	Chipped	-	6

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.