



Approved CR

IAA Salt Lake City
1800 South 1100 West
Branch No 342
Ogden, UT 84401-0258
(801) 399-2818/(801) 393-2325
WHOLESALE ASSESSMENT ONLY

Make/Model: **2018
HYUNDAI
IONIQ
HYBRID**

Bodystyle/Series: **4 Door Hatch
Back BLUE**

Color: **Silver**

Mileage: **67,247
(Verified)**

Turn-in Mileage: **-**

VIN: **KMHC65LC3JU076901**

Work Order/
Stock Number: **46369831**

Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**

Client Stock #: **G131527V**

Vehicle Grade : **Grade 3.1**

Remarks: **-**

Announcements: **-**

Certification : **-**

Req. Prev. Repair **-**

Order: **-**



Drivable: Yes

Equipment

Transmission:	-	A/C:	No
Engine:	4-Cylinder Hybrid	Cruise Control:	Yes
Engine Size:	1.6 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth/Vinyl /BLACK	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Buckets	Drive Type:	Front Wheel Drive
Seat Count:	-	Brakes:	Anti Lock Brakes

Equipment

Additional Equipment:

Car Tire Size - LF 195 / 65 R 15

Car Tire Size - RR 195 / 65 R 15

Car Tire Size - LR 195 / 65 R 15

Car Tire Size - RF 195 / 65 R 15

LF Tires - 7/32 inch

LR Tires - 7/32 inch

RF Tires - 7/32 inch

RR Tires - 6/32 inch

Tire Brand - Front Left - KUMHO

Tire Brand - Front Right - KUMHO

Tire Brand - Rear Left - KUMHO

Tire Brand - Rear Right - KUMHO

Tire Model - RR - Solus TA51A

Tire Model - RF - Solus TA51A

Tire Model - LR - Solus TA51A

Tire Model - LF - Solus TA51A

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Left Rear Wheel Cover	Chipped	-	2
	Instrument Panel	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Warning - Tire Pressure	On	-	Unacceptable
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Left Front Fender	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Front Bumper	Chipped	-	3
	Right Head Lamp	Faded	-	Repair Required
	Hood	Multiple Dents/Paint Damage	-	2
	Right Front Wheel Cover	Broken	-	Replacement Required
	Right Front Door	Chipped	-	3

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Rear Door	Chipped	-	2
	Rear Bumper	Heavy Scratch	-	2 To 3 Inches
	Right Rear Wheel Cover	Curb Rash	-	1 To 2 Inches
	Left Qtr Panel	Chipped	-	2
	Left Rear Door	Multiple Scratches Heavy	-	3
	Left Front Fender	Chipped	-	4

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Front Wheel Cover	Curb Rash	-	1/2 To 1 Inch
	Roof	Oxidized	-	> 12 Inches
	Left Drip Rail	Chipped	-	2
	Left Head Lamp	Faded	-	Repair Required

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.