



Approved CR

IAA Portage
W10321 State Road 16
Branch No 523
Portage, WI 53901
(608) 742-1515/(608) 742-6090
WHOLESALE ASSESSMENT ONLY

Make/Model: **2019 FORD
TRANSIT-150**
Bodystyle/Series: **Wagon XL**
Color: **Black**
Mileage: **46,035
(Verified)**
Turn-in Mileage: **-**
VIN: **1FMZK1ZMXKKB28519**
Work Order/
Stock Number: **45705947**
Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**
Client Stock #: **G422011W**
Vehicle Grade : **Grade 2.1**
Remarks: **-**
Announcements: **-**
Certification : **-**
Req. Prev. Repair **-**
Order: **-**



Drivable: Yes

Equipment


Transmission:	Automatic Transmission	A/C:	No
Engine:	6-Cylinder Gas	Cruise Control:	Yes
Engine Size:	3.7 L	Pwr Steering:	Yes
Roof:	Carriage	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /BLACK	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	3rd	Drive Type:	Rear Wheel Drive
Seat Count:	-	Brakes:	Anti Lock Brakes

Equipment


Additional Equipment:

Car Tire Size - LF 235 / 65 R 16	Car Tire Size - LR 235 / 65 R 16	Car Tire Size - RR 235 / 65 R 16
Car Tire Size - RF 235 / 65 R 16	LF Tires - 13/32 inch	LR Tires - 13/32 inch
RF Tires - 13/32 inch	RR Tires - 13/32 inch	Tire Brand - Front Left - FALKEN
Tire Brand - Front Right - FALKEN	Tire Brand - Rear Left - FALKEN	Tire Brand - Rear Right - FALKEN
Tire Model - RR - Wildpeak H/T (HT01A2) Oe	Tire Model - RF - Wildpeak H/T (HT01A2) Oe	Tire Model - LR - Wildpeak H/T (HT01A2) Oe
Tire Model - LF - Wildpeak H/T (HT01A2) Oe		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-
	Extra Photo 6	Photo Only	-	-
	Extra Photo 7	Photo Only	-	-
	Left Front Fender	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Qtr Glass	Missing	-	Replacement Required
	Front Ls Panel	Dent(S) W/ Paint Dmg	-	1/2 To 1 Inch
	Left Rear Window	Missing	-	Replacement Required

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Front Ls Panel Extension	Missing	-	Replacement Required
	Left Rear Wheel	Corrosion	-	1/2 To 1 Inch
	Left Front Fender	Chipped	-	6
	Left Front Wheel	Corrosion	-	> 12 Inches
	Windshield	Broken	-	Replacement Required
	Right Dutch Cargo Door	Heavy Scratch	-	1/2 To 1 Inch

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Front Window	Missing	-	Replacement Required
	Rear Ls Panel	Multiple Dents/Paint Damage	-	4
	Center Brake Light	Broken	-	Replacement Required
	Rear Roof Panel	Dent(S) W/ Paint Dmg	-	7 To 8 Inches
	Hood	Multiple Dents/Paint Damage	-	2
	Left Front Door	Heavy Scratch	-	1/2 To 1 Inch

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Drip Rail	Dent(S) W/ Paint Dmg	-	1/2 To 1 Inch
	Right Rear Wheel	Corrosion	-	3 To 4 Inches
	Left Rear Cargo Door	Dent(S) W/No Paint Dmg	-	5 To 6 Inches

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.