



Approved CR

IAA Dothan
15994 Us Highway 431 N
Branch No 731
Headland, AL 36345
(334) 693-4910/(334) 693-4920
WHOLESALE ASSESSMENT ONLY

Make/Model: **2019
HYUNDAI
IONIQ
HYBRID**

Bodystyle/Series: **4 Door Hatch
Back BLUE**

Color: **White**

Mileage: **29,123
(Verified)**

Turn-in Mileage: **-**

VIN: **KMHCC65LC5KU158405**

Work Order/
Stock Number: **46415183**

Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**

Client Stock #: **G132439W**

Vehicle Grade : **Grade 1.2**

Remarks: **-**

Announcements: **• Salvage**

Certification : **-**

Req. Prev. Repair **-**

Order: **-**



Drivable: Yes

Equipment

Transmission:	-	A/C:	No
Engine:	4-Cylinder Hybrid	Cruise Control:	Yes
Engine Size:	1.6 L	Pwr Steering:	Yes
Roof:	Hatchback	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /BLACK	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Buckets	Drive Type:	Front Wheel Drive
Seat Count:	-	Brakes:	Anti Lock Brakes

Equipment

Additional Equipment:

Car Tire Size - LF 195 / 65 R 15

Car Tire Size - LR 195 / 65 R 15

Car Tire Size - RR 195 / 65 R 15

Car Tire Size - RF 195 / 65 R 15

LF Tires - 10/32 inch

LR Tires - 10/32 inch

RF Tires - 10/32 inch

RR Tires - 10/32 inch

Tire Brand - Front Left - FIRESTONE

Tire Brand - Front Right - FIRESTONE

Tire Brand - Rear Left - FIRESTONE

Tire Brand - Rear Right - FIRESTONE

Tire Model - RR - All Season

Tire Model - RF - All Season

Tire Model - LR - All Season

Tire Model - LF - All Season

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Seats	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-
	Extra Photo 6	Photo Only	-	-
	Extra Photo 7	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Tail Light	Broken	-	Replacement Required
	Right Tail Light	Broken	-	Replacement Required
	Windshield	Broken	-	Replacement Required
	Left Front Fender	Dent(S) W/ Paint Dmg	-	5 To 6 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Roof	Severe Damage	-	Replacement Required
	Rear Glass	Broken	-	Replacement Required
	Left Brake Light	Broken	-	Replacement Required
	Lift Gate	Severe Damage	-	Replacement Required
	Left Qtr Panel	Severe Damage	-	Replacement Required
	Left Rear Door	Dent(S) W/ Paint Dmg	-	> 12 Inches

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Right Qtr Panel	Dent(S) W/ Paint Dmg	-	> 12 Inches
	Left Head Lamp	Faded	-	Repair Required
	Right Head Lamp	Faded	-	Repair Required
	Right Drip Rail	Dent(S) W/ Paint Dmg	-	> 12 Inches
	Rear Bumper	Broken	-	Replacement Required
	Left Rear Wheel Cover	Curb Rash	-	1/2 To 1 Inch

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.