



Approved CR

IAA Dothan
15994 Us Highway 431 N
Branch No 731
Headland, AL 36345
(334) 693-4910/(334) 693-4920
WHOLESALE ASSESSMENT ONLY

Make/Model: **2015 FORD
TRANSIT-150**
Bodystyle/Series: **Cargo Van -**
Color: **White**
Mileage: **71,000
(Verified)**
Turn-in Mileage: **-**
VIN: **1FTNE1YM7FKB30133**
Work Order/
Stock Number: **46370928**
Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**
Client Stock #: **G43A4836**
Vehicle Grade : **Grade 2.9**
Remarks: **-**
Announcements: **-**
Certification : **-**
Req. Prev. Repair **-**
Order: **-**



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	6-Cylinder Gas	Cruise Control:	No
Engine Size:	3.7 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /GRAY	Rear Defroster:	No
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Buckets	Drive Type:	Rear Wheel Drive
Seat Count:	-	Brakes:	Anti Lock Brakes

Equipment

Additional Equipment:

Car Tire Size - LF 235 / 65 R 16

Car Tire Size - LR 235 / 65 R 16

Car Tire Size - RR 235 / 65 R 16

Car Tire Size - RF 235 / 65 R 16

LF Tires - 14/32 inch

LR Tires - 13/32 inch

RF Tires - 14/32 inch

RR Tires - 12/32 inch

Tire Brand - Front Left - FIRESTONE

Tire Brand - Front Right - FIRESTONE

Tire Brand - Rear Left - FIRESTONE

Tire Brand - Rear Right - FIRESTONE

Tire Model - RR - transforce cv2

Tire Model - RF - transforce cv2

Tire Model - LR - transforce cv2

Tire Model - LF - transforce cv2

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Seats	Photo Only	-	-
	Odometer	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Right Front Fender	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 3	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Keys	Photo Only	-	-
	Engine	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Head Lamp	Faded	-	Repair Required
	Left Front Seat Cushion	Torn	-	7 To 8 Inches
	Front Ls Panel	Dent(S) W/ Paint Dmg	-	1/2 To 1 Inch
	Shifter Knob	Worn	-	Replacement Required
	Right Head Lamp	Faded	-	Repair Required
	Right Tail Light	Water Damage	-	Replacement Required

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Left Tail Light	Water Damage	-	Replacement Required
	Roof	Enviro Paint Damage	-	> 12 Inches
	Steering Wheel	Worn	-	Replacement Required
	Right Front Seat Cushion	Stained	-	Permanent

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.