
Approved CR

Dealers Auto Auction of Mobile
3030 McVay Drive North
Mobile, AL 36606
2513387653
WHOLESALE ASSESSMENT ONLY



Make/Model:	**2020 CHEVROLET TAHOE**
Bodystyle/Series:	**4 Door Sport Utility Vehicle LS 4D SUV 4WD**
Color:	**WHITE**
Mileage:	**92,566 (Verified, 6 digits)**
Turn-in Mileage:	-
VIN:	**1GNSKAEC4LR105840**
Work Order/ Stock Number:	**000594495**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**623701W**
Vehicle Grade :	**Grade 4.3**
AutoGrade :	**4.3 - Clean**
Remarks:	-
Announcements:	-
Certification :	**Not Certified**
Req. Prev. Repair Order:	-

Drivable: Yes

UniBody/Frame Damage: NO As Is 100K Miles: NO

Equipment

Transmission:	**Automatic Transmission**	A/C:	**Yes**
Engine:	**8-Cylinder Gas**	Cruise Control:	**Yes**
Engine Size:	**5.3 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**Yes**
Radio:	**AM/FM Radio**	Pwr Windows	**Yes**
Interior - Type/Color:	**Cloth Interior /BLACK**	Rear Defroster:	**Yes**
Airbag:	**Dual Air Bags**	Tilt Steering:	**Yes**
Seats:	**Power**	Drive Type:	**4-Wheel Drive**
Seat Count:	-	Brakes:	**Power Brakes**

Equipment

Additional Equipment:

4 Wheel Drive	4 Wheel Drive	ABS Brakes
Air Conditioning	Automatic Headlights	Bluetooth Connection
Brake Assist System	Car Tire Size - Hood	Car Tire Size - LF tire size P265/65R18
Car Tire Size - LR tire size P265/65R18	Car Tire Size - RF tire size P265/65R18	Car Tire Size - RR tire size P265/65R18
Child Safety Locks	Cruise Control	Cylinders - 8
Daytime Running Lights	Driver Air Bag	Floor Mats
HD Radio	Heated Mirrors	Independent Climate Control
Intermittent Wipers	Keyless Entry	Keyless Start
LF Tires - 6/32 inch	LR Tires - 6/32 inch	Leather Steering Wheel
MP3 Radio	Master Key - 2key(s)	Motor Fuel Type - Gas
Pass-Through Rear Seat	Pass. Air Bag	Power Brakes
Power Driver & Passenger Seat	Power Driver Seat	Power Lock
Power Mirrors	Power Steering	Power Windows
Privacy Glass	RF Tires - 6/32 inch	RR Tires - 6/32 inch
Rain Sensor	Rear AC	Rear Defrost
Rear Parking Aid	Reverse Camera	Running Board
Seat Trim - Cloth	Security System	Side Airbags - Front
Side Airbags - Rear	Spare Tire	Steering Wheel Audio Control
Stereo - AM/FM Radio	Tilt Steering Wheel	Tilt Wheel
Tire Brand - Front Left - L qtr panel	Tire Brand - Front Left - LF tire mfg Other	Tire Brand - Front Right - RF tire mfg Other
Tire Brand - Rear Left - LR tire mfg Other	Tire Brand - Rear Right - RR tire mfg Other	Tire Pressure Monitor System
Tow Hitch	Traction Control	Transmission - Automatic Transmission w/ Overdrive
Wheels Front Left - Aluminium	Wheels Front Right - Aluminium	Wheels Rear Left - Aluminium
Wheels Rear Right - Aluminium		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Trunk	Photo Only	Estimate Only	Unknown
	Left Front Fender	Photo Only	Estimate Only	Unknown

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Front Fender	Photo Only	Estimate Only	Unknown
	Right Qtr Panel	Photo Only	Estimate Only	Unknown
	Left Qtr Panel	Photo Only	Estimate Only	Unknown
	Hood	Photo Only	Estimate Only	Unknown
	Extra Photo 2	Photo Only	Estimate Only	Unknown
	Extra Photo 3	Photo Only	Estimate Only	Unknown
	Photo - Wheel	Photo Only	Estimate Only	Unknown
	Photo - Deck	Photo Only	Estimate Only	Unknown
	Photo - Vin/Id Sticker	Photo Only	Estimate Only	Unknown
	Steering Wheel	Photo Only	Estimate Only	Unknown
	Stereo	Photo Only	Estimate Only	Unknown
	Left Rear Seat	Photo Only	Estimate Only	Unknown
	Extra Photo 1	Photo Only	Estimate Only	Unknown

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Front	Photo Only	Estimate Only	Unknown
	Photo - Interior	Photo Only	Estimate Only	Unknown
	Photo - Dash	Photo Only	Estimate Only	Unknown
	Overall Picture - Engine	Photo Only	Estimate Only	Unknown
	Overall Picture - Odometer	Photo Only	Estimate Only	Unknown
	Roof	Photo Only	Estimate Only	Unknown
	Keys	Photo Only	Estimate Only	Unknown
	Door Panels	Photo Only	Estimate Only	Unknown
	Left Front Tire	Photo Only	Estimate Only	Unknown
	Photo - Rear	Photo Only	Estimate Only	Unknown
	Right Front Tire	Photo Only	Estimate Only	Unknown
	Right Rear Tire	Photo Only	Estimate Only	Unknown
	Left Rear Tire	Photo Only	Estimate Only	Unknown

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Front Valance	Loose	Repair	Repair Required
	Front Bumper	Chipped	Repair	6
	Hood	Chipped	Repair	6
	Lift Gate	Multiple Scratches Heavy	Repair	5
	Rear Bumper	Multiple Scratches Heavy	Repair	5
	Right Front Fender	Chipped	Repair	5

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.