
Approved CR

Mid Kansas Auto Auction Wichita
4716 S. Santa Fe
Wichita , KS 67216
316-500-7700/316-500-7701
codyd@mksaa.com
WHOLESALE ASSESSMENT ONLY



Make/Model:	**2018 DODGE GRAND CARAVAN**
Bodystyle/Series:	**Van SE WAGON**
Color:	**SILVER**
Mileage:	**63,523 (Verified, 6 digits)**
Turn-in Mileage:	-
VIN:	**2C4RDGBG0JR255592**
Work Order/ Stock Number:	**000116314**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	-
Vehicle Grade :	**Grade 2.4**
AutoGrade :	**2.4 - Below Average**
Remarks:	-
Announcements:	• (O) Hail Damage
Certification :	**Not Certified**
Req. Prev. Repair Order:	-

Drivable: Yes

UniBody/Frame Damage: NO As Is 100K Miles: NO

Equipment

Transmission:	**Automatic Transmission**	A/C:	**Yes**
Engine:	**6-Cylinder Flex Fuel**	Cruise Control:	**Yes**
Engine Size:	**3.6 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**Yes**
Radio:	-	Pwr Windows	**Yes**
Interior - Type/Color:	**Cloth Interior /BLACK**	Rear Defroster:	**Yes**
Airbag:	**Dual Air Bags**	Tilt Steering:	**Yes**
Seats:	-	Drive Type:	**Front Wheel Drive**
Seat Count:	-	Brakes:	**Power Brakes**

Equipment

Additional Equipment:

2nd Row Bucket Seats	3rd Row Seat	4th Passenger Door
ABS Brakes	Air Conditioning	Bluetooth Connection
Brake Assist System	Car Tire Size - RF tire size P225/65SR17	Car Tire Size - RR tire size P225/65SR17
Car Tire Size - LF tire size P225/65SR17	Car Tire Size - LR tire size P225/65SR17	Child Safety Locks
Cruise Control	Cylinders - 6	Daytime Running Lights
Driver Air Bag	Dual Air Conditioning	Electrochromic Rearview Mirror
Empty Weight - 4321 lb	Engine Immobilizer	Floor Mats
Front Wheel Drive	Front Wheel Drive	Hard Disk Drive Media Storage
Heated Mirrors	Intermittent Wipers	Keyless Entry
LF Tires - 5/32 inch	LR Tires - 7/32 inch	Leather Steering Wheel
MP3 Radio	Master Key - 1key(s)	Motor Fuel Type - Other
Pass. Air Bag	Power Brakes	Power Lock
Power Mirrors	Power Steering	Power Windows
Privacy Glass	RF Tires - 4/32 inch	RR Tires - 8/32 inch
Rear AC	Rear Defrost	Rear Spoiler
Reverse Camera	Seat Trim - Cloth	Side Airbags - Front
Spare Tire	Steering Wheel Audio Control	Tilt Steering Wheel
Tire Brand - Front Left - LF tire mfg Firestone	Tire Brand - Front Right - RF tire mfg Firestone	Tire Brand - Rear Left - LR tire mfg Firestone
Tire Brand - Rear Right - RR tire mfg Firestone	Tire Pressure Monitor System	Traction Control
Transmission - Automatic Transmission	Trip Computer	Wheels Front Left - Steel
Wheels Front Right - Steel	Wheels Rear Left - Steel	Woodgrain Interior Package

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 4	Photo Only	Estimate Only	Unknown
	Photo - Deck	Photo Only	Estimate Only	Unknown
	Photo - Vin/Id Sticker	Photo Only	Estimate Only	Unknown

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Stereo	Photo Only	Estimate Only	Unknown
	Left Rear Seat	Photo Only	Estimate Only	Unknown
	3rd Row Seat	Photo Only	Estimate Only	Unknown
	Roof	Photo Only	Estimate Only	Unknown
	Keys	Photo Only	Estimate Only	Unknown
	Deck Lid Badge	Photo Only	Estimate Only	Unknown
	Extra Photo 2	Photo Only	Estimate Only	Unknown
	Extra Photo 1	Photo Only	Estimate Only	Unknown
	Photo - Interior	Photo Only	Estimate Only	Unknown
	Photo - Dash	Photo Only	Estimate Only	Unknown
	Overall Picture - Engine	Photo Only	Estimate Only	Unknown
	Overall Picture - Odometer	Photo Only	Estimate Only	Unknown
	Photo - Wheel	Photo Only	Estimate Only	Unknown

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 3	Photo Only	Estimate Only	Unknown

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Front Bumper/Cover	Chipped	Touch Up	7
	Hood	Corrosion	Refinish	> 12 Inches
	Hood	Hail Damage	PDR	10 Or More
	Left Qtr Panel	Multiple Dents/No Paint Damage	PDR	8
	Lift Gate	Multiple Dents/No Paint Damage	PDR	Pdr-4 Dents
	Left Front Door	Multiple Dents/No Paint Damage	PDR	Pdr-5 Dents
	Left Front Fender	Dent(S) W/ Paint Dmg	Refinish	3 To 4 Inches
	Left Front Fender	Multiple Dents/No Paint Damage	PDR	Pdr-4 Dents
	Left Rear Door	Multiple Dents/No Paint Damage	PDR	Pdr-3 Dents
	Left Rear Door	Multiple Dents/Paint Damage	Refinish	3
	Right Qtr Panel	Multiple Dents/Paint Damage	Repair	6

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Roof	Multiple Dents/No Paint Damage	PDR	10 Or More
	Right Front Door	Chipped	Touch Up	4
	Right Front Fender	Chipped	Touch Up	3
	Right Rear Door	Multiple Dents/Paint Damage	Repair	4

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.