
Approved
CR

Dealers Auto Auction of Mobile
3030 McVay Drive North
Mobile, AL 36606
2513387653
WHOLESALE ASSESSMENT ONLY



Make/Model:	**2019 HYUNDAI IONIQ HYBRID**
Bodystyle/Series:	**4 Door Sedan BLUE 4D HATCHBACK**
Color:	**WHITE**
Mileage:	**64,454 (Verified, 6 digits)**
Turn-in Mileage:	-
VIN:	**KMHC65LC7KU158440**
Work Order/ Stock Number:	**000592660**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**13-2540W**
Vehicle Grade :	**Grade 4.0**
AutoGrade :	**4.0 - Clean**
Remarks:	-
Announcements:	-
Certification :	**Not Certified**
Req. Prev. Repair Order:	-

Drivable: Yes

UniBody/Frame Damage: NO As Is 100K Miles: NO

Equipment

Transmission:	**Automatic Transmission**	A/C:	**Yes**
Engine:	**4-Cylinder Hybrid**	Cruise Control:	**Yes**
Engine Size:	**1.6 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**Yes**
Radio:	**AM/FM Radio**	Pwr Windows	**Yes**
Interior - Type/Color:	**Cloth Interior /GRAY**	Rear Defroster:	**Yes**
Airbag:	**Dual Air Bags**	Tilt Steering:	**Yes**
Seats:	-	Drive Type:	**Front Wheel Drive**
Seat Count:	-	Brakes:	**Power Brakes**

Equipment

Additional Equipment:

ABS Brakes	Air Conditioning	Automatic Headlights
Bluetooth Connection	Brake Assist System	Car Tire Size - LR tire size P195/65HR15
Car Tire Size - Hood	Car Tire Size - RR tire size P195/65HR15	Car Tire Size - RF tire size P195/65HR15
Car Tire Size - LF tire size P195/65HR15	Child Safety Locks	Cruise Control
Cylinders - 4	Daytime Running Lights	Driver Air Bag
Empty Weight - 2996 lb	Engine Immobilizer	Floor Mats
Front Wheel Drive	Front Wheel Drive	HD Radio
Independent Climate Control	Intermittent Wipers	Keyless Entry
Keyless Start	LF Tires - 7/32 inch	LR Tires - 7/32 inch
MP3 Radio	Master Key - 2key(s)	Motor Fuel Type - Other
Pass-Through Rear Seat	Pass. Air Bag	Power Brakes
Power Lock	Power Mirrors	Power Steering
Power Windows	RF Tires - 7/32 inch	RR Tires - 7/32 inch
Rear Defrost	Rear Spoiler	Reverse Camera
Seat Trim - Cloth	Security System	Side Airbags - Front
Smart Key - 2key(s)	Steering Wheel Audio Control	Stereo - AM/FM Radio
Tilt Steering Wheel	Tilt Wheel	Tire Brand - Front Left - LF tire mfg Other
Tire Brand - Front Left - L qtr panel	Tire Brand - Front Right - RF tire mfg Other	Tire Brand - Rear Left - LR tire mfg Other
Tire Brand - Rear Right - RR tire mfg Other	Tire Pressure Monitor System	Traction Control
Transmission - Automatic Transmission	Trip Computer	Wheels Front Left - Steel
Wheels Front Right - Steel	Wheels Rear Left - Steel	

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Interior	Photo Only	Estimate Only	Unknown
	Photo - Front	Photo Only	Estimate Only	Unknown
	Extra Photo 3	Photo Only	Estimate Only	Unknown

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Wheel	Photo Only	Estimate Only	Unknown
	Photo - Deck	Photo Only	Estimate Only	Unknown
	Photo - Vin/Id Sticker	Photo Only	Estimate Only	Unknown
	Steering Wheel	Photo Only	Estimate Only	Unknown
	Stereo	Photo Only	Estimate Only	Unknown
	Overall Picture - Engine	Photo Only	Estimate Only	Unknown
	Overall Picture - Odometer	Photo Only	Estimate Only	Unknown
	Left Rear Seat	Photo Only	Estimate Only	Unknown
	Roof	Photo Only	Estimate Only	Unknown
	Keys	Photo Only	Estimate Only	Unknown
	Door Panels	Photo Only	Estimate Only	Unknown
	Left Front Tire	Photo Only	Estimate Only	Unknown
	Photo - Rear	Photo Only	Estimate Only	Unknown

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Front Tire	Photo Only	Estimate Only	Unknown
	Right Rear Tire	Photo Only	Estimate Only	Unknown
	Left Rear Tire	Photo Only	Estimate Only	Unknown
	Trunk	Photo Only	Estimate Only	Unknown
	Left Front Fender	Photo Only	Estimate Only	Unknown
	Right Front Fender	Photo Only	Estimate Only	Unknown
	Right Qtr Panel	Photo Only	Estimate Only	Unknown
	Left Qtr Panel	Photo Only	Estimate Only	Unknown
	Hood	Photo Only	Estimate Only	Unknown
	Extra Photo 2	Photo Only	Estimate Only	Unknown
	Extra Photo 1	Photo Only	Estimate Only	Unknown
	Photo - Dash	Photo Only	Estimate Only	Unknown

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Front Bumper	Chipped	Repair	5
	Hood	Chipped	Repair	4
	Lift Gate	Enviro Paint Damage	Report	> 12 Inches
	Left Front Door	Dent(S) W/ Paint Dmg	Repair	1 To 2 Inches
	Rear Bumper	Multiple Scratches Heavy	Repair	4
	Right Front Fender	Chipped	Repair	5

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.