Approved CR

IAA Louisville North
891 Ballardsville Road
Branch No 669
Eminence, KY 40019
(502) 215-4804
WHOLESALE ASSESSMENT ONLY



Make/Model:	**2018 FORD TRANSIT-350**
Bodystyle/Series:	**Wagon XL**
Color:	**White**
Mileage:	**65,610 (Verified)**
Turn-in Mileage:	-
VIN:	**1FBZX2YM0JKB07212**
Work Order/ Stock Number:	**46382856**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G431558U**
Vehicle Grade :	**Grade 2.6**
Remarks:	-
Announcements:	-
Certification :	-
Req. Prev. Repair Order:	-

Drivable: No

Equipment

Transmission:	**Automatic Transmission**	A/C:	**No**
Engine:	**6-Cylinder Gas**	Cruise Control:	**Yes**
Engine Size:	**3.7 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**Yes**
Radio:	-	Pwr Windows	**Yes**
Interior - Type/Color:	**Cloth/Vinyl /GRAY**	Rear Defroster:	**Yes**
Airbag:	**Driver Side Air Bag**	Tilt Steering:	**Yes**
Seats:	**5th**	Drive Type:	**Rear Wheel Drive**
Seat Count:	-	Brakes:	**Disc**

Equipment

Additional Equipment:

Car Tire Size - LF 235 / 65 R 16	Car Tire Size - LR 235 / 65 R 16	Car Tire Size - RR 235 / 65 R 16
Car Tire Size - RF 235 / 65 R 16	LF Tires - 8/32 inch	LR Tires - 9/32 inch
RF Tires - 8/32 inch	RR Tires - 9/32 inch	Tire Brand - Front Left - GOODYEAR
Tire Brand - Front Right - DELINTE	Tire Brand - Rear Left - DELINTE	Tire Brand - Rear Right - DELINTE
Tire Model - RR - Wrangler HT	Tire Model - RF - Wrangler HT	Tire Model - LR - Wrangler HT
Tire Model - LF - Wrangler HT		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Keys	Photo Only	-	-
	Engine	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Odometer	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Photo - Dash	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Rear Bumper/Cover	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
[no photo]	Personally Identifiable Info	De-Identify	-	-
	Extra Photo 2	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Right Side Panel	Photo Only	-	-

Chargeable Damages

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Fuel Door	Misaligned	-	Repair Required
	Shifter Knob	Worn	-	Replacement Required
	Steering Wheel	Worn	-	Replacement Required
	Roof	Multiple Dents/No Paint Damage	-	5
	Left Front Wheel	Corrosion	-	7 To 8 Inches
	Left Rear Wheel	Corrosion	-	1 To 2 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Rear Wheel	Corrosion	-	1 To 2 Inches
	Right Front Wheel	Corrosion	-	3 To 4 Inches
	Overall Vehicle	De-Identify	-	Removal Required
	Left Head Lamp	Faded	-	Repair Required
	Front Bumper Cover Upper	Multiple Scratches Light	-	3

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.