



Approved
CR

IAA St. Louis
2436 Old Country Inn Dr.
Branch No 524
Caseyville, IL 62232
(618) 797-0200/(618) 797-0001
WHOLESALE ASSESSMENT ONLY

Make/Model: **2022
CHEVROLET
TAHOE
Sport Utility**

Bodystyle/Series: **Vehicle 4WD
COMMERCIAL
FLEET**

Color: **Black**

Mileage: **121,640
(Verified)**

Turn-in Mileage: **-**

VIN: **1GNSKLED1NR238045**

Work Order/
Stock Number: **46236407**

Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**

Client Stock #: **G621772Z**

Vehicle Grade : **Grade 3.7**

Remarks: **-**

Announcements:

**• WINDSHIELD
CRACKED**

Certification : **-**

Req. Prev. Repair **-**

Order:



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	8-Cylinder Gas	Cruise Control:	Yes
Engine Size:	5.3 L	Pwr Steering:	Yes
Roof:	Carriage	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /BLACK	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Buckets	Drive Type:	4-Wheel Drive
Seat Count:	-	Brakes:	Anti Lock Brakes

Equipment

Additional Equipment:

Car Tire Size - RR 265 / 65 R 18

Car Tire Size - RF 265 / 65 R 18

Car Tire Size - LF 265 / 65 R 18

Car Tire Size - LR 265 / 65 R 18

LF Tires - 9/32 inch

LR Tires - 6/32 inch

RF Tires - 8/32 inch

RR Tires - 7/32 inch

Tire Brand - Front Left - GENERAL

Tire Brand - Front Right - GENERAL

Tire Brand - Rear Left - GENERAL

Tire Brand - Rear Right - GENERAL

Tire Model - LF - Grabber GT

Tire Model - LR - Grabber GT

Tire Model - RF - Grabber GT

Tire Model - RR - Grabber GT

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Right Front Fender	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Front Wheel	Curb Rash	-	2 To 3 Inches
	Right Front Wheel	Curb Rash	-	> 12 Inches

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Windshield	Broken	-	Replacement Required
	Left Rear Wheel	Curb Rash	-	1 To 2 Inches
	Left Rear Door	Dent(S) W/No Paint Dmg	-	Pdr-1 Dent
	Right Rear Wheel	Curb Rash	-	7 To 8 Inches

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.