Approved CR

IAA Spokane
3520 N Tschirley Rd
Branch No 322
Spokane, WA 99224
(509)891-2388/(855)631-9008
WHOLESALE ASSESSMENT ONLY



Make/Model:	**2017 RAM 1500**
	-
Bodystyle/Series:	**TRADESMAN 4X4 6`4 BOX**
Color:	**Blue**
Mileage:	**51,180 (Verified)**
Turn-in Mileage:	-
VIN:	**1C6RR7FG8HS544277**
Work Order/ Stock Number:	**46447708**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G624813S**
Vehicle Grade :	**Grade 3.8**
Remarks:	-
Announcements:	-
Certification :	-
Req. Prev. Repair Order:	-

Drivable: Yes

Equipment

Transmission:	**Automatic Transmission**	A/C:	**No**
Engine:	**6-Cylinder Flex Fuel**	Cruise Control:	**Yes**
Engine Size:	**3.6 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**Yes**
Radio:	-	Pwr Windows	**Yes**
Interior - Type/Color:	**Cloth Interior /GRAY**	Rear Defroster:	**Yes**
Airbag:	**Driver Side Air Bag**	Tilt Steering:	**Yes**
Seats:	**Bench**	Drive Type:	**4-Wheel Drive**
Seat Count:	-	Brakes:	**Anti Lock Brakes**

Equipment

Additional Equipment:

Car Tire Size - LF 265 / 70 R 17	Car Tire Size - LR 265 / 70 R 17	Car Tire Size - RR 265 / 70 R 17
Car Tire Size - RF 265 / 70 R 17	LF Tires - 6/32 inch	LR Tires - 4/32 inch
RF Tires - 7/32 inch	RR Tires - 4/32 inch	Tire Brand - Front Left - GOODYEAR
Tire Brand - Front Right - GOODYEAR	Tire Brand - Rear Left - GOODYEAR	Tire Brand - Rear Right - GOODYEAR
Tire Model - RR - Wrangler Duratrac	Tire Model - RF - Wrangler Duratrac	Tire Model - LR - Wrangler Duratrac
Tire Model - LF - Wrangler Duratrac		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Keys	Photo Only	-	-
	Engine	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Odometer	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Dash	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Instrument Panel	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Front Cover Center	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Front Metal Bumper Painted	Chipped	-	10 Or More
	Vinyl Floor	Loose	-	Repair Required
	Inside Bed	Multiple Scratches Heavy	-	10 Or More

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.