



Approved
CR

America's Auto Auction - Richmond
3600 Deepwater Terminal Road
Richmond, VA 23234
804-232-7355/804-232-1818
richmond.fleet@americasaa.com
WHOLESALE ASSESSMENT ONLY

Make/Model: **2020 HYUNDAI
SANTA FE**
4 Door Sport
Bodystyle/Series: **Utility Vehicle**
SE 4D SUV
AWD 2.4L
Color: **BLACK**
Mileage: **93,228 (Verified,
6 digits)**
Turn-in Mileage: **-**
VIN: **5NMS2CAD8LH280812**
Work Order/
Stock Number: **000845013**
Customer: **GSA Fleet Vehicle Sales**
1800 F Street NW
Washington, DC 20405
fleetsalessupport@gsa.gov
Client Stock #: **G61-5210Q**
Vehicle Grade : **Grade 2.8**
Remarks: **-**
Announcements:

- CEL -
- TRANSMISSION
- CLUTCH
- SOLENOID
- PRIOR POLICE
- BROKEN
- WINDSHIELD

Certification : **Not Certified**
Req. Prev. Repair **-**
Order:



Drivable: Yes

UniBody/Frame Damage: NO As Is 100K Miles: NO

Equipment

Transmission:	Automatic Transmission	A/C:	Yes
Engine:	4-Cylinder Gas	Cruise Control:	Yes
Engine Size:	2.4 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	AM/FM Radio	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /BLACK	Rear Defroster:	Yes

Equipment

Airbag:	Dual Air Bags	Tilt Steering:	Yes
Seats:	-	Drive Type:	All Wheel Drive
Seat Count:	-	Brakes:	Power Brakes
Additional Equipment:			
ABS Brakes	Adaptive Cruise Control	Air Conditioning	
All Wheel Drive	Automatic Headlights	Bluetooth Connection	
Brake Assist System	Car Tire Size - LR tire size P235/65TR17	Car Tire Size - RF tire size P235/65TR17	
Car Tire Size - RR tire size P235/65TR17	Car Tire Size - LF tire size P235/65TR17	Child Safety Locks	
Collision Avoidance	Cruise Control	Cylinders - 4	
Daytime Running Lights	Driver Air Bag	Empty Weight - 3735 lb	
Floor Mats	Intermittent Wipers	Keyless Entry	
LF Tires - 6/32 inch	LR Tires - 7/32 inch	Lane Departure System	
MP3 Radio	Master Key - 1key(s)	Motor Fuel Type - Gas	
Pass-Through Rear Seat	Pass. Air Bag	Power Brakes	
Power Lock	Power Mirrors	Power Steering	
Power Windows	Privacy Glass	RF Tires - 5/32 inch	
RR Tires - 10/32 inch	Rear Defrost	Rear Spoiler	
Reverse Camera	Seat Trim - Cloth	Security System	
Side Airbags - Front	Spare Tire	Steering Wheel Audio Control	
Stereo - AM/FM Radio	Tilt Steering Wheel	Tire Brand - Front Left - LF tire mfg Goodyear	
Tire Brand - Front Right - RF tire mfg Goodyear	Tire Brand - Rear Left - LR tire mfg Goodyear	Tire Brand - Rear Right - RR tire mfg Arizonian	
Tire Pressure Monitor System	Traction Control	Transmission - Automatic Transmission	
Trip Computer	Wheels Front Left - Aluminium	Wheels Front Right - Aluminium	
Wheels Rear Left - Aluminium	Wheels Rear Right - Aluminium		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 2	Photo Only	Estimate Only	Unknown
	Photo - Rear	Photo Only	Estimate Only	Unknown


Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Door Panels	Photo Only	Estimate Only	Unknown
	Keys	Photo Only	Estimate Only	Unknown
	Roof	Photo Only	Estimate Only	Unknown
	Left Rear Seat	Photo Only	Estimate Only	Unknown
	Stereo	Photo Only	Estimate Only	Unknown
	Steering Wheel	Photo Only	Estimate Only	Unknown
	Photo - Vin/Id Sticker	Photo Only	Estimate Only	Unknown
	Photo - Deck	Photo Only	Estimate Only	Unknown
	Extra Photo 4	Photo Only	Estimate Only	Unknown
	Extra Photo 3	Photo Only	Estimate Only	Unknown
	Photo - Wheel	Photo Only	Estimate Only	Unknown
	Overall Picture - Odometer	Photo Only	Estimate Only	Unknown
	Overall Picture - Engine	Photo Only	Estimate Only	Unknown

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Dash	Photo Only	Estimate Only	Unknown
	Photo - Interior	Photo Only	Estimate Only	Unknown
	Extra Photo 1	Photo Only	Estimate Only	Unknown

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Front Fender	Heavy Scratch	Repair	1/2 To 1 Inch
	Rear Bumper	Broken	Replace	Replacement Required
	Right Qtr Panel	Heavy Scratch	Repair	5 To 6 Inches
	Left Rear Door	Heavy Scratch	Repair	2 To 3 Inches
	Left Front Door	Heavy Scratch	Repair	11 To 12 Inches
	Left Qtr Panel	Dent(S) W/No Paint Dmg	PDR	2 To 3 Inches
	Cargo Shelf	Aftermarket	Remove	Removal Required
	Windshield	Broken	Replace	Replacement Required
	Right Rear Door	Dent(S) W/ Paint Dmg	Repair	> 12 Inches

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.