Approved CR

IAA Denver East
8510 Brighton Rd.
Branch No 374
Commerce City, CO 80022
(303) 287-9737/(303) 287-1214
WHOLESALE ASSESSMENT ONLY



Make/Model:	**2018 CHEVROLET EXPRESS 2500**
Bodystyle/Series:	**Cargo Van WORK VAN**
Color:	**White**
Mileage:	**2,138 (Verified)**
Turn-in Mileage:	-
VIN:	**1GCWGAFG2J1272948**
Work Order/ Stock Number:	**46333790**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G430101V**
Vehicle Grade :	**Grade 4.3**
Remarks:	-
Announcements:	-
Certification :	-
Req. Prev. Repair Order:	-

Drivable: Yes

Equipment

Transmission:	**Automatic Transmission**	A/C:	**No**
Engine:	**8-Cylinder Flex Fuel**	Cruise Control:	**Yes**
Engine Size:	**6 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**Yes**
Radio:	-	Pwr Windows	**Yes**
Interior - Type/Color:	**Cloth Interior /GRAY**	Rear Defroster:	**Yes**
Airbag:	**Driver Side Air Bag**	Tilt Steering:	**Yes**
Seats:	**3rd**	Drive Type:	**Rear Wheel Drive**
Seat Count:	-	Brakes:	**Disc**

Equipment

Additional Equipment:

Car Tire Size - LF 245 / 75 R 16	Car Tire Size - LR 245 / 75 R 16	Car Tire Size - RR 245 / 75 R 16
Car Tire Size - RF 245 / 75 R 16	LF Tires - 10/32 inch	LR Tires - 10/32 inch
RF Tires - 10/32 inch	RR Tires - 10/32 inch	Tire Brand - Front Left - BRIDGESTONE
Tire Brand - Front Right - BRIDGESTONE	Tire Brand - Rear Left - BRIDGESTONE	Tire Brand - Rear Right - BRIDGESTONE
Tire Model - RF - V-Steel RLB 265	Tire Model - LR - V-Steel RLB 265	Tire Model - LF - V-Steel RLB 265
Tire Model - RR - V-Steel RLB 265		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Metal Bumper Painted	Multiple Scratches Heavy	-	4

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.