



Approved CR

IAA Tulsa
5311 W 46th Street S
Branch No 436
Tulsa, OK 74107
(918) 445-4691/(918) 445-4905
WHOLESALE ASSESSMENT ONLY

Make/Model: **2017 FORD
F-350**

Bodystyle/Series: **Crew Cab XL**

Color: **White**

Mileage: **90,717
(Verified)**

Turn-in Mileage: **-**

VIN: **1FD8W3B62HED72812**

Work Order/
Stock Number: **46299569**

Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**

Client Stock #: **G631180U**

Vehicle Grade : **Grade 1.4**

Remarks: **-**

Announcements:

- Active Codes
see IAA
Condition
Report

Certification : **-**

Req. Prev. Repair **-**

Order: **-**



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	8-Cylinder Gas	Cruise Control:	No
Engine Size:	6.2 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	No
Radio:	-	Pwr Windows	No
Interior - Type/Color:	Leather/Cloth Interior /GRAY	Rear Defroster:	No
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Bench	Drive Type:	4-Wheel Drive
Seat Count:	-	Brakes:	Disc

Equipment

Additional Equipment:

Car Tire Size - RR 245 / 75 R 17	Car Tire Size - RF 245 / 75 R 17	Car Tire Size - LF 245 / 75 R 17
Car Tire Size - LR 245 / 75 R 17	LF Tires - 7/32 inch	LR Tires - 7/32 inch
RF Tires - 16/32 inch	RR Tires - 7/32 inch	Tire Brand - Front Left - GOODYEAR
Tire Brand - Front Right - GOODYEAR	Tire Brand - Rear Left - GOODYEAR	Tire Brand - Rear Right - GOODYEAR
Tire Model - LF - Wrangler Workhorse At	Tire Model - LR - Wrangler Workhorse At	Tire Model - RF - Wrangler Workhorse At
Tire Model - RR - Wrangler Workhorse At		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Keys	Photo Only	-	-
	Engine	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Warning - Tire Pressure	On	-	Unacceptable
	Left Rear Door Panel	Multiple Scratches Light	-	3
	Right Rear Rail	Previous Repair	-	Acceptable
	Left Rear Rail	Previous Repair	-	Acceptable
	Pickup Bed	Aftermarket	-	Acceptable
	Rear Seats	Photo Only	-	-

Chargeable Damages

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Bed Side	Dent(S) W/ Paint Dmg	-	1/2 To 1 Inch
	Right Front Wheel	Corrosion	-	4 To 5 Inches
	Hood	Multiple Dents/Paint Damage	-	6
	Front Metal Bumper Painted	Multiple Scratches Heavy	-	3
	Left Bed Side	Peeling	-	5 To 6 Inches
	Inside Bed	Rust	-	> 12 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Steering Wheel	Worn	-	Replacement Required
	Left Front Seat Cushion	Torn	-	2 To 3 Inches
	Left Front Wheel	Corrosion	-	1 To 2 Inches
	Left Rear Wheel	Corrosion	-	1 To 2 Inches
	Tailgate	Multiple Scratches Heavy	-	8
	Right Rear Wheel	Curb Rash	-	9 To 10 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Metal Bumper Painted	Rust	-	> 12 Inches

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.