



Approved CR

IAA Tulsa
5311 W 46th Street S
Branch No 436
Tulsa, OK 74107
(918) 445-4691/(918) 445-4905
WHOLESALE ASSESSMENT ONLY

Make/Model: **2017 FORD
TRANSIT-150**
Bodystyle/Series: **Wagon XL**
Color: **White**
Mileage: **17,275
(Verified)**
Turn-in Mileage: **-**
VIN: **1FMZK1ZM7HKB26638**
Work Order/
Stock Number: **46299563**
Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**
Client Stock #: **G420467U**
Vehicle Grade : **Grade 3.6**
Remarks: **-**
Announcements: **-**
Certification : **-**
Req. Prev. Repair **-**
Order:



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	6-Cylinder Gas	Cruise Control:	Yes
Engine Size:	3.7 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /BLACK	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	5th	Drive Type:	Rear Wheel Drive
Seat Count:	-	Brakes:	Disc

Equipment

Additional Equipment:

Car Tire Size - LF 235 / 65 R 16

Car Tire Size - LR 235 / 65 R 16

Car Tire Size - RR 235 / 65 R 16

Car Tire Size - RF 235 / 65 R 16

LF Tires - 10/32 inch

LR Tires - 10/32 inch

RF Tires - 8/32 inch

RR Tires - 8/32 inch

Tire Brand - Front Left - TOYO

Tire Brand - Front Right - TOYO

Tire Brand - Rear Left - TOYO

Tire Brand - Rear Right - TOYO

Tire Model - RR - Celsius Cargo

Tire Model - RF - Celsius Cargo

Tire Model - LR - Celsius Cargo

Tire Model - LF - Celsius Cargo

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Seats	Photo Only	-	-
	Warning - Tire Pressure	On	-	Unacceptable
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
[no photo]	Personally Identifiable Info	De-Identify	-	-
	Right Front Fender	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Odometer	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Photo - Dash	Photo Only	-	-

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Left Drip Rail	Rust	-	> 12 Inches
	Hood	Chipped	-	2

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.