



Approved CR

IAA Tulsa
5311 W 46th Street S
Branch No 436
Tulsa, OK 74107
(918) 445-4691/(918) 445-4905
WHOLESALE ASSESSMENT ONLY

Make/Model: **2018 FORD
TRANSIT-350**
Bodystyle/Series: **Wagon XL**
Color: **White**
Mileage: **44,622
(Verified)**
Turn-in Mileage: **-**
VIN: **1FBZX2ZM4JKB42950**
Work Order/
Stock Number: **46299568**
Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalessupport@gsa.gov**
Client Stock #: **G431274V**
Vehicle Grade : **Grade 3.1**
Remarks: **-**
Announcements: **-**
Certification : **-**
Req. Prev. Repair **-**
Order:



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	6-Cylinder Gas	Cruise Control:	Yes
Engine Size:	3.7 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /BLACK	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	5th	Drive Type:	Rear Wheel Drive
Seat Count:	-	Brakes:	Disc

Equipment

Additional Equipment:

Car Tire Size - LF 235 / 60 R 16	Car Tire Size - LR 235 / 60 R 16	Car Tire Size - RR 235 / 60 R 16
Car Tire Size - RF 235 / 60 R 16	LF Tires - 9/32 inch	LR Tires - 3/32 inch
RF Tires - 7/32 inch	RR Tires - 10/32 inch	Tire Brand - Front Left - NEXEN
Tire Brand - Front Right - NEXEN	Tire Brand - Rear Left - NEXEN	Tire Brand - Rear Right - NEXEN
Tire Model - RR - Roadian CT8 HL	Tire Model - RF - Roadian CT8 HL	Tire Model - LR - Roadian CT8 HL
Tire Model - LF - Roadian CT8 HL		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
[no photo]	Personally Identifiable Info	De-Identify	-	-
	Right Front Fender	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
-------	------	--------	--------	----------

Chargeable Damages

Photo	Item	Damage	Action	Severity
 Tire Information Driver Front Size: 205 / 60 R 16 Brand: HEDON Tread Depth: 1/32" Model: Roadstar C70 H6 Driver Rear Size: 205 / 60 R 16 Brand: HEDON Tread Depth: 1/32" Model: Roadstar C70 H6 Passenger Front Size: 205 / 60 R 16 Brand: HEDON Tread Depth: 1/32" Model: Roadstar C70 H6 Passenger Rear Size: 205 / 60 R 16 Brand: HEDON Tread Depth: 1/32" Model: Roadstar C70 H6	Left Rear Tire	Worn	-	Replacement Required
	Right Qtr Panel	Multiple Dents/Paint Damage	-	2
	Left Rear Cargo Door	Chipped	-	2
	Roof	Rust	-	> 12 Inches
	Left Front Seat Cushion	Stained	-	Permanent

Transportation Damages

Photo	Item	Damage	Action	Severity
[no photo]	Personally Identifiable Info	De-Identify	-	-

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.