



Approved CR

Mountain State Auto Auction
Interstate I-79, Exit 125
5546 Benedum Drive
Shinnston, WV 26431
(304) 592-5300/(304) 592-2286
WHOLESALE ASSESSMENT ONLY

Make/Model: **2021
HYUNDAI
SONATA
HYBRID
4 Door Sedan**

Bodystyle/Series: **BLUE 4D
SEDAN**

Color: **BLACK**

Mileage: **1 (Verified, 6
digits)**

Turn-in Mileage: **-**

VIN: **KMHL24JJ3MA030854**

Work Order/
Stock Number: **000299199**

Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**

Client Stock #: **G10-0018Y**

Vehicle Grade : **Grade 0.3**

AutoGrade : **0.0 - Extra
Rough**

Remarks: **-**

Announcements: **-**

Certification : **Not Certified**

Req. Prev. Repair **-**

Order:



Drivable: No

UniBody/Frame Damage: NO As Is 100K Miles: NO

Equipment

Transmission:	Automatic Transmission	A/C:	Yes
Engine:	4-Cylinder Hybrid	Cruise Control:	Yes
Engine Size:	2 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	AM/FM Radio	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /GRAY	Rear Defroster:	Yes
Airbag:	Dual Air Bags	Tilt Steering:	Yes
Seats:	-	Drive Type:	Front Wheel Drive
Seat Count:	-	Brakes:	Power Brakes

Equipment

Additional Equipment:

ABS Brakes	Adaptive Cruise Control	Air Conditioning
Automatic Headlights	Blind Spot Monitor	Bluetooth Connection
Brake Assist System	Car Tire Size - RR tire size P205/65HR16	Car Tire Size - RF tire size P205/65HR16
Car Tire Size - LR tire size P205/65HR16	Car Tire Size - LF tire size P205/65HR16	Child Safety Locks
Collision Avoidance	Cruise Control	Cylinders - 4
Daytime Running Lights	Driver Air Bag	Empty Weight - 3325 lb
Engine Immobilizer	Floor Mats	Front Wheel Drive
Front Wheel Drive	HD Radio	Independent Climate Control
Intermittent Wipers	Keyless Entry	Keyless Start
LED Headlights	LF Tires - 4/32 inch	LR Tires - 6/32 inch
Lane Departure System	MP3 Radio	Motor Fuel Type - Other
Pass-Through Rear Seat	Pass. Air Bag	Power Brakes
Power Lock	Power Mirrors	Power Steering
Power Trunk/Liftgate	Power Windows	RF Tires - 2/32 inch
RR Tires - 6/32 inch	Rear Defrost	Rear Spoiler
Remote Trunk Release	Reverse Camera	Seat Trim - Cloth
Security System	Side Airbags - Front	Side Airbags - Rear
Steering Wheel Audio Control	Stereo - AM/FM Radio	Telematics
Tilt Steering Wheel	Tilt Wheel	Tire Brand - Front Left - LF tire mfg Other
Tire Brand - Front Right - RF tire mfg Other	Tire Brand - Rear Left - LR tire mfg Other	Tire Brand - Rear Right - RR tire mfg Other
Tire Pressure Monitor System	Traction Control	Transmission - Automatic Transmission
Trip Computer	Turn Signal Mirrors	Wheels Front Left - Aluminium
Wheels Front Right - Aluminium	Wheels Rear Left - Aluminium	Wheels Rear Right - Aluminium

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Roof	Photo Only	Estimate Only	Unknown
	Extra Photo 2	Photo Only	Estimate Only	Unknown

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 1	Photo Only	Estimate Only	Unknown
	Photo - Interior	Photo Only	Estimate Only	Unknown
	Photo - Vin/Id Sticker	Photo Only	Estimate Only	Unknown
	Left Rear Seat	Photo Only	Estimate Only	Unknown
	Extra Photo 3	Photo Only	Estimate Only	Unknown

Chargeable Damages

Photo	Item	Damage	Action	Severity
[no photo]	Right Front Tire	Worn	Replace	Replacement Required
[no photo]	Air Bags	Deployed	Replace	Replacement Required
[no photo]	Deck Lid	Broken	Replace	Replacement Required
[no photo]	Engine	Inoperable	Report	Repair Required
[no photo]	Front Bumper/Cover	Broken	Replace	Replacement Required
[no photo]	Grille	Broken	Replace	Replacement Required
[no photo]	Left A Pillar	Broken	Replace	Replacement Required
[no photo]	Left Head Lamp	Broken	Replace	Replacement Required
[no photo]	Left Qtr Panel	Broken	Replace	Replacement Required
[no photo]	Left Rear Rail	Kinked	Repair	> 12 Inches
[no photo]	Left Rocker Panel	Broken	Replace	Replacement Required
[no photo]	Left Front Door	Broken	Replace	Replacement Required
[no photo]	Left Front Fender	Broken	Replace	Replacement Required
[no photo]	Left Rear Door	Broken	Replace	Replacement Required
[no photo]	Left Tail Light	Broken	Replace	Replacement Required
[no photo]	Left Rear Wheel	Broken	Replace	Replacement Required
[no photo]	Right Qtr Panel	Broken	Replace	Replacement Required
[no photo]	Right Rear Rail	Kinked	Repair	> 12 Inches
[no photo]	Rear Bumper/Cover	Broken	Replace	Replacement Required
[no photo]	Rear Glass	Broken	Replace	Replacement Required
[no photo]	Roof	Broken	Replace	Replacement Required
[no photo]	Right Tail Light	Broken	Replace	Replacement Required
[no photo]	Transmission	Inoperable	Report	Repair Required
[no photo]	Windshield	Broken	Replace	Replacement Required

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.