



Approved CR

IAA Tifton
368 Oak Ridge Church Rd
Branch No 703
Tifton, GA 31794
(229) 386-2640/(229) 386-2650
WHOLESALE ASSESSMENT ONLY

Make/Model: **2016
CHEVROLET
COLORADO**

Bodystyle/Series: **Extended Cab
WT**

Color: **Brown**

Mileage: **26,543
(Verified)**

Turn-in Mileage: **-**

VIN: **1GCHSBEA2G1263153**

Work Order/
Stock Number: **46245699**

Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**

Client Stock #: **G413118S**

Vehicle Grade : **Grade 1.5**

Remarks: **-**

Announcements:

• Check
Engine Light

Certification : **-**

Req. Prev. Repair **-**

Order: **-**



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	4-Cylinder Gas	Cruise Control:	No
Engine Size:	2.5 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /GRAY	Rear Defroster:	No
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Bench	Drive Type:	Rear Wheel Drive
Seat Count:	-	Brakes:	Hydraulic Brakes

Equipment

Additional Equipment:

Car Tire Size - LF 265 / 70 R 16

Car Tire Size - LR 265 / 70 R 16

Car Tire Size - RR 265 / 70 R 16

Car Tire Size - RF 265 / 70 R 16

LF Tires - 8/32 inch

LR Tires - 6/32 inch

RF Tires - 5/32 inch

RR Tires - 5/32 inch

Tire Brand - Front Left - FIRESTONE

Tire Brand - Front Right - FIRESTONE

Tire Brand - Rear Left - FIRESTONE

Tire Brand - Rear Right - FIRESTONE

Tire Model - RR - Destination LE3

Tire Model - RF - Destination LE3

Tire Model - LR - Destination LE3

Tire Model - LF - Destination LE3

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Dash	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Rear Bumper/Cover	Photo Only	-	-
	Warning Light - Engine	On	-	Unacceptable
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 2	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Hood	Peeling	-	> 12 Inches
	Left Head Lamp	Faded	-	Repair Required
	Right Head Lamp	Faded	-	Repair Required
	Right Front Fender	Peeling	-	> 12 Inches
	Right Rear Wheel	Peeling	-	4 To 5 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Rear Wheel	Corrosion	-	2 To 3 Inches
	Left Front Fender	Dent(S) W/No Paint Dmg	-	3 To 4 Inches
	Left Front Wheel	Corrosion	-	1/2 To 1 Inch
	Left Drip Rail	Peeling	-	> 12 Inches
	Roof	Peeling	-	> 12 Inches
	Front Center Armrest	Torn	-	> 12 Inches

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Right Front Door	Peeling	-	> 12 Inches
	Right Rear Door	Peeling	-	> 12 Inches

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.