Original CR

IAA Honolulu
91-445A Komohana St
Branch No 114
Kapolei, HI 96707
(808) 682-2858/(808) 682-3988
WHOLESALE ASSESSMENT ONLY



Make/Model:	**2006 CHEVROLET SILVERADO 1500**
Bodystyle/Series:	**- LS**
Color:	**Champagne**
Mileage:	**57,003 (Verified)**
Turn-in Mileage:	-
VIN:	**1GCEC14Z06E261426**
Work Order/ Stock Number:	**46544305**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G42B0639**
Vehicle Grade :	**Grade 1.5**
Remarks:	-
Announcements:	• PARTS MAY BE MISSING • NON GSA OWNED VEHICLE • REPAIR HISTORY NOT AVAILABLE. CONDITION UNKNOWN • REPAIRS MAY BE NEEDED R
Certification :	-
Req. Prev. Repair Order:	-

Drivable: Yes

Equipment

Transmission:	**Automatic Transmission w/ Overdrive**	A/C:	**No**
Engine:	**8-Cylinder Flex Fuel**	Cruise Control:	**No**
Engine Size:	**5.3 L**	Pwr Steering:	**Yes**


Equipment

Roof:	**Hard Top**	Pwr Locks:	**No**
Radio:	-	Pwr Windows	**No**
Interior - Type/Color:	**Cloth Interior /GRAY**	Rear Defroster:	**No**
Airbag:	**Driver Side Air Bag**	Tilt Steering:	**Yes**
Seats:	**Bench**	Drive Type:	**Rear Wheel Drive**
Seat Count:	-	Brakes:	**Hydraulic Brakes**

Additional Equipment:

Car Tire Size - LF 245 / 70 R 17	Car Tire Size - LR 245 / 70 R 17	Car Tire Size - RR 245 / 70 R 17
Car Tire Size - RF 245 / 70 R 17	LF Tires - 8/32 inch	LR Tires - 10/32 inch
RF Tires - 13/32 inch	RR Tires - 9/32 inch	Tire Brand - Front Left - SUMITOMO
Tire Brand - Front Right - SUMITOMO	Tire Brand - Rear Left - SUMITOMO	Tire Brand - Rear Right - SUMITOMO
Tire Model - RR - Encounter HT2	Tire Model - RF - Encounter HT2	Tire Model - LR - Encounter HT2
Tire Model - LF - Encounter HT2		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Cd Player	Aftermarket	-	Acceptable
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-
	Extra Photo 6	Photo Only	-	-
	Left Front Fender	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Warning Light - Engine	On	-	Unacceptable

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Tail Light	Heavy Scratch	-	Replacement Required

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Roof	Rust	-	2 To 3 Inches
	Tailgate Handle Bezel	Missing	-	Replacement Required
	Right Bed Side	Dent(S) W/ Paint Dmg	-	> 12 Inches
	Dash	Broken	-	Replacement Required
	Left Head Lamp	Faded	-	Repair Required
	Right Head Lamp	Faded	-	Repair Required

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Rear Center Cap	Missing	-	Replacement Required
	Tailgate	Peeling	-	> 12 Inches
	Right Tail Light	Heavy Scratch	-	Replacement Required
	Left Front Fender	Dent(S) W/ Paint Dmg	-	4 To 5 Inches
	Front Bumper Cover Upper	Broken	-	Replacement Required
	Headlining	Worn	-	Replacement Required

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Steering Wheel	Worn	-	Replacement Required
	Inside Bed	Dent(S) W/ Paint Dmg	-	> 12 Inches
	Tailgate Molding	Broken	-	Replacement Required
	Cab - Left	Dent(S) W/ Paint Dmg	-	> 12 Inches
	Left Bed Side	Dent(S) W/ Paint Dmg	-	1/8 To 1/2 Inch
	Left Front Door	Dent(S) W/ Paint Dmg	-	< 1/8 Inch

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Metal Bumper Chrome	Dent(S) W/No Paint Dmg	-	3 To 4 Inches

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.