Approved CR

America`s Auto Auction - Richmond
3600 Deepwater Terminal Road
Richmond, VA 23234
804-232-7355/804-232-1818
richmond.fleet@americasaa.com
WHOLESALE ASSESSMENT ONLY



Make/Model:	**2019 HYUNDAI SONATA**
Bodystyle/Series:	**4 Door Sedan ECO 4D SEDAN**
Color:	**GRAY**
Mileage:	**17,989 (Verified, 6 digits)**
Turn-in Mileage:	-
VIN:	**5NPE24AA6KH774869**
Work Order/ Stock Number:	**000845477**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G100485V**
Vehicle Grade :	**Grade 5.0**
Remarks:	-
Announcements:	-
Certification :	**Not Certified**
Req. Prev. Repair Order:	-

Drivable: Yes

UniBody/Frame Damage: NO As Is 100K Miles: NO

Equipment

Transmission:	**Automatic Transmission**	A/C:	**Yes**
Engine:	**4-Cylinder Gas Turbo**	Cruise Control:	**Yes**
Engine Size:	**1.6 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**Yes**
Radio:	**AM/FM Radio**	Pwr Windows	**Yes**
Interior - Type/Color:	**Cloth Interior /GRAY**	Rear Defroster:	**Yes**
Airbag:	**Dual Air Bags**	Tilt Steering:	**Yes**
Seats:	-	Drive Type:	**Front Wheel Drive**
Seat Count:	-	Brakes:	**Power Brakes**

Equipment


Additional Equipment:

ABS Brakes	Air Conditioning	Automatic Headlights
Blind Spot Monitor	Bluetooth Connection	Brake Assist System
Car Tire Size - LF tire size P205/65HR16	Car Tire Size - RR tire size P205/65HR16	Car Tire Size - RF tire size P205/65HR16
Car Tire Size - LR tire size P205/65HR16	Child Safety Locks	Cruise Control
Cylinders - 4	Daytime Running Lights	Driver Air Bag
Empty Weight - 3247 lb	Floor Mats	Front Wheel Drive
Front Wheel Drive	Intermittent Wipers	Keyless Entry
LF Tires - 10/32 inch	LR Tires - 10/32 inch	MP3 Radio
Master Key - 2key(s)	Motor Fuel Type - Gas	Pass-Through Rear Seat
Pass. Air Bag	Power Brakes	Power Lock
Power Mirrors	Power Steering	Power Windows
RF Tires - 10/32 inch	RR Tires - 10/32 inch	Rear Defrost
Remote Trunk Release	Reverse Camera	Seat Trim - Cloth
Security System	Side Airbags - Front	Spare Tire
Steering Wheel Audio Control	Stereo - AM/FM Radio	Tilt Steering Wheel
Tire Pressure Monitor System	Traction Control	Transmission - Automatic Transmission
Trip Computer	Turbocharged	Wheels Front Left - Aluminium
Wheels Front Right - Aluminium	Wheels Rear Left - Aluminium	Wheels Rear Right - Aluminium


Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Interior	Photo Only	Estimate Only	Unknown
	Photo - Dash	Photo Only	Estimate Only	Unknown
	Overall Picture - Engine	Photo Only	Estimate Only	Unknown
	Overall Picture - Odometer	Photo Only	Estimate Only	Unknown

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Wheel	Photo Only	Estimate Only	Unknown
	Extra Photo 3	Photo Only	Estimate Only	Unknown
	Photo - Deck	Photo Only	Estimate Only	Unknown
	Photo - Vin/Id Sticker	Photo Only	Estimate Only	Unknown
	Steering Wheel	Photo Only	Estimate Only	Unknown
	Stereo	Photo Only	Estimate Only	Unknown
	Left Rear Seat	Photo Only	Estimate Only	Unknown
	Roof	Photo Only	Estimate Only	Unknown
	Keys	Photo Only	Estimate Only	Unknown
	Door Panels	Photo Only	Estimate Only	Unknown
	Photo - Rear	Photo Only	Estimate Only	Unknown
	Extra Photo 2	Photo Only	Estimate Only	Unknown
	Extra Photo 1	Photo Only	Estimate Only	Unknown

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Hood	Chipped	Touch Up	2

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.