



Approved CR

IAA Kansas City
2663 S 88th Street
Branch No 527
Kansas City, KS 66111
(913) 422-9303/(913) 422-7421
WHOLESALE ASSESSMENT ONLY

Make/Model: **2019
HYUNDAI
IONIQ
HYBRID**

Bodystyle/Series: **4 Door Hatch
Back BLUE**

Color: **Silver**

Mileage: **77,842
(Verified)**

Turn-in Mileage: **-**

VIN: **KMHC65LC1KU156408**

Work Order/
Stock Number: **46302108**

Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**

Client Stock #: **G130167W**

Vehicle Grade : **Grade 1.5**

Remarks: **-**

Announcements:

**• HAIL
DAMAGE**

Certification : **-**

Req. Prev. Repair **-**

Order: **-**



Drivable: Yes

Equipment


Transmission:	-	A/C:	No
Engine:	4-Cylinder Hybrid	Cruise Control:	Yes
Engine Size:	1.6 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth/Vinyl /BLACK	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Buckets	Drive Type:	Front Wheel Drive
Seat Count:	-	Brakes:	Anti Lock Brakes

Equipment

Additional Equipment:

Car Tire Size - LF 195 / 65 R 15	Car Tire Size - LR 195 / 65 R 15	Car Tire Size - RR 195 / 65 R 15
Car Tire Size - RF 195 / 65 R 15	LF Tires - 8/32 inch	LR Tires - 10/32 inch
RF Tires - 8/32 inch	RR Tires - 10/32 inch	Tire Brand - Front Left - KELLY
Tire Brand - Front Right - KELLY	Tire Brand - Rear Left - KELLY	Tire Brand - Rear Right - KELLY
Tire Model - RR - edge touring plus	Tire Model - RF - edge touring plus	Tire Model - LR - edge touring plus
Tire Model - LF - edge touring plus		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Extra Photo 6	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 4	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Keys	Photo Only	-	-
	Engine	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Seats	Photo Only	-	-
	Right Front Fender	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Front Wheel Cover	Curb Rash	-	1/8 To 1/2 Inch
	Left Rear Wheel Cover	Curb Rash	-	1/2 To 1 Inch
	Left Qtr Panel	Hail Damage	-	3
	Right Front Wheel Cover	Curb Rash	-	2 To 3 Inches
	Left Mirror	Broken	-	Replacement Required

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Roof	Hail Damage	-	10 Or More
	Left Drip Rail	Hail Damage	-	10 Or More
	Hood	Hail Damage	-	10 Or More
	Front Bumper	Heavy Scratch	-	4 To 5 Inches
	Left Head Lamp	Faded	-	Repair Required
	Right Head Lamp	Faded	-	Repair Required

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Lf Mirror Cover	Chipped	-	2
	Right Front Door	Hail Damage	-	3
	Right Rear Door	Hail Damage	-	10 Or More
	Right Qtr Panel	Hail Damage	-	10 Or More
	Deck Lid	Peeling	-	> 12 Inches

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.