



Approved CR

IAA Spokane
3520 N Tschirley Rd
Branch No 322
Spokane, WA 99224
(509)891-2388/(855)631-9008
WHOLESALE ASSESSMENT ONLY

Make/Model: **2016 FORD
F-250**

Bodystyle/Series: **Extended Cab
XL**

Color: **White**

Mileage: **31,787
(Verified)**

Turn-in Mileage: **-**

VIN: **1FT7X2B63GED02984**

Work Order/
Stock Number: **46294338**

Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**

Client Stock #: **G631784S**

Vehicle Grade : **Grade 2.3**

Remarks: **-**

Announcements:

- MISSING
TAILGATE
- WARNING
INDICATOR
LIGHT ON
(SEE IAA
CONDITION
REPORT
FOR
DETAILS)

Certification : **-**

Req. Prev. Repair **-**

Order:



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	8-Cylinder Gas	Cruise Control:	Yes
Engine Size:	6.2 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Vinyl Interior /GRAY	Rear Defroster:	No

Equipment

Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Bench	Drive Type:	4-Wheel Drive
Seat Count:	-	Brakes:	Anti Lock Brakes


Additional Equipment:

Car Tire Size - LF 245 / 75 R 17	Car Tire Size - LR 245 / 75 R 17	Car Tire Size - RR 245 / 75 R 17
Car Tire Size - RF 245 / 75 R 17	LF Tires - 3/32 inch	LR Tires - 3/32 inch
RF Tires - 2/32 inch	RR Tires - 3/32 inch	Tire Brand - Front Left - SAILUN
Tire Brand - Front Right - SAILUN	Tire Brand - Rear Left - SAILUN	Tire Brand - Rear Right - SAILUN
Tire Model - LF - Terramax HLT	Tire Model - RF - Terramax HLT	Tire Model - RR - Terramax HLT
Tire Model - LR - Terramax HLT		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Warning - Tire Pressure	On	-	Unacceptable

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Head Lamp	Faded	-	Acceptable
	Left Front Tire	Worn	-	Replacement Required
	Left Front Seat	Torn	-	> 12 Inches
	Left Front Fender	Dent(S) W/ Paint Dmg	-	> 12 Inches

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Rear Bumper	Missing	-	Replacement Required
	Tailgate	Missing	-	Replacement Required
	Right Rear Tire	Worn	-	Replacement Required
	Right Front Tire	Worn	-	Replacement Required
	Left Rear Tire	Worn	-	Replacement Required
	Left Head Lamp	Faded	-	Acceptable

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.