



Approved CR

IAA Macon  
2200 Trade Ave.  
Branch No 734  
Macon, GA 31217  
(478) 314-0031/(478) 314-0040  
WHOLESALE ASSESSMENT ONLY

Make/Model: **2018  
CHEVROLET  
SILVERADO  
2500HD**

Bodystyle/Series: **Crew Cab  
WT**

Color: **Silver**

Mileage: **36,274  
(Verified)**

Turn-in Mileage: **-**

VIN: **1GC1KUEGXJF239131**

Work Order/  
Stock Number: **46356704**

Customer: **GSA Fleet Vehicle Sales  
1800 F Street NW  
Washington, DC 20405  
fleetsalesupport@gsa.gov**

Client Stock #: **G630892V**

Vehicle Grade : **Grade 2.7**

Remarks: **-**

Announcements: **-**

Certification : **-**

Req. Prev. Repair **-**

Order: **-**



Drivable: Yes

### Equipment

|                        |                               |                 |                         |
|------------------------|-------------------------------|-----------------|-------------------------|
| Transmission:          | <b>Automatic Transmission</b> | A/C:            | <b>No</b>               |
| Engine:                | <b>8-Cylinder Flex Fuel</b>   | Cruise Control: | <b>Yes</b>              |
| Engine Size:           | <b>6 L</b>                    | Pwr Steering:   | <b>Yes</b>              |
| Roof:                  | <b>Hard Top</b>               | Pwr Locks:      | <b>Yes</b>              |
| Radio:                 | <b>-</b>                      | Pwr Windows     | <b>Yes</b>              |
| Interior - Type/Color: | <b>Cloth/Vinyl /GRAY</b>      | Rear Defroster: | <b>No</b>               |
| Airbag:                | <b>Driver Side Air Bag</b>    | Tilt Steering:  | <b>Yes</b>              |
| Seats:                 | <b>Bench</b>                  | Drive Type:     | <b>4-Wheel Drive</b>    |
| Seat Count:            | <b>-</b>                      | Brakes:         | <b>Anti Lock Brakes</b> |

## Equipment

### Additional Equipment:

Car Tire Size - RR 245 / 75 R 17

Car Tire Size - RF 245 / 75 R 17

Car Tire Size - LF 245 / 75 R 17

Car Tire Size - LR 245 / 75 R 17

LF Tires - 0/32 inch

LR Tires - 0/32 inch

RF Tires - 0/32 inch

RR Tires - 3/32 inch

Tire Brand - Front Left - FIRESTONE

Tire Brand - Front Right - FIRESTONE

Tire Brand - Rear Left - FIRESTONE

Tire Brand - Rear Right - FIRESTONE

Tire Model - LF - Transforce HT

Tire Model - LR - Transforce HT

Tire Model - RF - Transforce HT

Tire Model - RR - Transforce HT

## Non Chargeable Damages

| Photo                                                                               | Item                   | Damage     | Action | Severity |
|-------------------------------------------------------------------------------------|------------------------|------------|--------|----------|
|    | Photo - Vin/Id Sticker | Photo Only | -      | -        |
|    | Engine                 | Photo Only | -      | -        |
|   | Keys                   | Photo Only | -      | -        |
|  | Front Cover Center     | Photo Only | -      | -        |
|  | Right Side Panel       | Photo Only | -      | -        |
|  | Left Side Panel        | Photo Only | -      | -        |
|  | Instrument Panel       | Photo Only | -      | -        |
|  | Rear Bumper            | Photo Only | -      | -        |

### Non Chargeable Damages

| Photo                                                                               | Item                    | Damage     | Action | Severity |
|-------------------------------------------------------------------------------------|-------------------------|------------|--------|----------|
|    | Extra Photo 2           | Photo Only | -      | -        |
|    | Extra Photo 3           | Photo Only | -      | -        |
|    | Right Front Fender      | Photo Only | -      | -        |
|    | Extra Photo 4           | Photo Only | -      | -        |
|    | Extra Photo 5           | Photo Only | -      | -        |
|   | Extra Photo 6           | Photo Only | -      | -        |
|  | Left Front Fender       | Photo Only | -      | -        |
|  | Left Rear Bumper/Cover  | Photo Only | -      | -        |
|  | Right Rear Bumper/Cover | Photo Only | -      | -        |
|  | Photo - Dash            | Photo Only | -      | -        |
|  | Extra Photo 1           | Photo Only | -      | -        |

### Non Chargeable Damages

| Photo                                                                             | Item                    | Damage     | Action | Severity     |
|-----------------------------------------------------------------------------------|-------------------------|------------|--------|--------------|
|  | Odometer                | Photo Only | -      | -            |
|  | Rear Seats              | Photo Only | -      | -            |
|  | Warning - Tire Pressure | On         | -      | Unacceptable |

### Chargeable Damages

| Photo                                                                               | Item                    | Damage                   | Action | Severity             |
|-------------------------------------------------------------------------------------|-------------------------|--------------------------|--------|----------------------|
|   | Inside Bed              | Multiple Scratches Heavy | -      | 10 Or More           |
|  | Tailgate Protective Cap | Cracked                  | -      | Replacement Required |
|  | Cab - Left              | Dent(S) W/ Paint Dmg     | -      | 1/2 To 1 Inch        |
|  | Right Rear Wheel        | Curb Rash                | -      | 9 To 10 Inches       |

### Chargeable Damages

| Photo                                                                               | Item              | Damage                   | Action | Severity             |
|-------------------------------------------------------------------------------------|-------------------|--------------------------|--------|----------------------|
|    | Left Bed Side     | Multiple Scratches Light | -      | 5                    |
|    | Left Rear Tire    | Worn                     | -      | Replacement Required |
|    | Left Rocker Panel | Dent(S) W/ Paint Dmg     | -      | 1 To 2 Inches        |
|   | Left Front Tire   | Worn                     | -      | Replacement Required |
|  | Hood              | Chipped                  | -      | 2                    |
|  | Right Cab Side    | Dent(S) W/No Paint Dmg   | -      | 1/2 To 1 Inch        |

### Chargeable Damages

| Photo                                                                              | Item                  | Damage               | Action | Severity             |
|------------------------------------------------------------------------------------|-----------------------|----------------------|--------|----------------------|
|   | Right Bed Side        | Dent(S) W/ Paint Dmg | -      | 9 To 10 Inches       |
|   | Right Front Tire      | Worn                 | -      | Replacement Required |
|   | Right Rear Tire       | Worn                 | -      | Replacement Required |
|  | Tailgate Handle Bezel | Loose                | -      | Repair Required      |

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.