



Approved
CR

United Auto Exchange
3710 Prescott Rd
Memphis, TN 38118
9017957634
jcraig@uaxmemphis.com
WHOLESALE ASSESSMENT ONLY

Make/Model: 2018
HYUNDAI
IONIQ
HYBRID
4 Door Sedan
Bodystyle/Series: BLUE 4D
HATCHBACK
Color: SILVER
Mileage: 36,057
(Verified, 6
digits)
Turn-in Mileage: -
VIN: KMHC65LC2JU077344
Work Order/
Stock Number: 000082319
Customer: GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov
Client Stock #: G132642V
Vehicle Grade : Grade 3.9
Remarks: -

Announcements:

- DEFICIENCIES, WHEN KNOWN, HAVE BEEN NOTED IN THE ITEM DESCRIPTION
- HOWEVER, THE ABSENCE OF ANY INDICATED DEFICIENCIES
- DOES NOT MEAN THERE ARE NONE.

Certification : Not Certified
Req. Prev. Repair
Order: -



Drivable: Yes

UniBody/Frame Damage: NO As Is 100K Miles: NO

Equipment

Equipment			
Transmission:	Automatic Transmission	A/C:	Yes
Engine:	4-Cylinder Hybrid	Cruise Control:	Yes
Engine Size:	1.6 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	AM/FM Radio	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /GRAY	Rear Defroster:	Yes
Airbag:	Dual Air Bags	Tilt Steering:	Yes
Seats:	-	Drive Type:	Front Wheel Drive
Seat Count:	-	Brakes:	Power Brakes
Additional Equipment:			
ABS Brakes	Air Conditioning	Automatic Headlights	
Bluetooth Connection	Brake Assist System	Car Tire Size - LF tire size 195/65R15	
Car Tire Size - RR tire size 195/65R15	Car Tire Size - RF tire size 195/65R15	Car Tire Size - LR tire size 195/65R15	
Child Safety Locks	Cruise Control	Cylinders - 4	
Daytime Running Lights	Driver Air Bag	Empty Weight - 2996 lb	
Engine Immobilizer	Floor Mats	Front Wheel Drive	
Front Wheel Drive	HD Radio	Independent Climate Control	
Intermittent Wipers	Keyless Entry	Keyless Start	
LF Tires - 8/32 inch	LR Tires - 5/32 inch	MP3 Radio	
Master Key - 1key(s)	Motor Fuel Type - Other	Pass-Through Rear Seat	
Pass. Air Bag	Power Brakes	Power Lock	
Power Mirrors	Power Steering	Power Windows	
RF Tires - 12/32 inch	RR Tires - 3/32 inch	Rear Defrost	
Rear Spoiler	Reverse Camera	Seat Trim - Cloth	
Security System	Side Airbags - Front	Steering Wheel Audio Control	
Stereo - AM/FM Radio	Tilt Steering Wheel	Tilt Wheel	
Tire Brand - Front Left - LF tire mfg MICHELIN	Tire Brand - Front Right - RF tire mfg SOLARUS	Tire Brand - Rear Left - LR tire mfg MICHELIN	
Tire Brand - Rear Right - RR tire mfg MICHELIN	Tire Pressure Monitor System	Traction Control	
Transmission - Automatic Transmission	Trip Computer		

Non Chargeable Damages

Non Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Extra Photo 1	Photo Only	Estimate Only	Unknown
	Roof	Photo Only	Estimate Only	Unknown
	Photo - Rear	Photo Only	Estimate Only	Unknown
	Extra Photo 4	Photo Only	Estimate Only	Unknown
	Extra Photo 5	Photo Only	Estimate Only	Unknown
	Extra Photo 6	Photo Only	Estimate Only	Unknown
	Left Rear Seat	Photo Only	Estimate Only	Unknown
	Overall Picture - Odometer	Photo Only	Estimate Only	Unknown
	Photo - Dash	Photo Only	Estimate Only	Unknown
	Photo - Vin/Id Sticker	Photo Only	Estimate Only	Unknown
	Extra Photo 2	Photo Only	Estimate Only	Unknown
	Overall Picture - Engine	Photo Only	Estimate Only	Unknown

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Wheel	Photo Only	Estimate Only	Unknown
	Extra Photo 7	Photo Only	Estimate Only	Unknown
	Extra Photo 3	Photo Only	Estimate Only	Unknown
	Photo - Deck	Photo Only	Estimate Only	Unknown
	Frame	Photo Only	Estimate Only	Unknown
	Left Front Tire	Photo Only	Estimate Only	Unknown
	Left Rear Tire	Photo Only	Estimate Only	Unknown
	Right Rear Tire	Photo Only	Estimate Only	Unknown
	Right Front Tire	Photo Only	Estimate Only	Unknown
	Photo - Interior	Photo Only	Estimate Only	Unknown

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Windshield	Star In Glass	Report	2 To 3 Inches

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Left Head Lamp	Faded	Report	Repair Required
	Front Bumper/Cover	Hole(S)	Report	3 To 4 Inches
	Left Qtr Panel	Multiple Scratches Heavy	Report	3
	Left Rear Door	Dent(S) W/No Paint Dmg	Report	Pdr-1 Dent
	Right Head Lamp	Faded	Report	Repair Required
	Right Rear Door	Dent(S) W/ Paint Dmg	Report	1/8 To 1/2 Inch

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.