



Approved CR

IAA North Virginia
15 Le Way Drive
Branch No 723
Fredericksburg, VA 22406
(540) 373-7800/(540) 371-4123
WHOLESALE ASSESSMENT ONLY

Make/Model: **2020 DODGE
CHARGER**
Bodystyle/Series: **4 Door Sedan
SXT RWD**
Color: **Black**
Mileage: **76,473
(Verified)**
Turn-in Mileage: **-**
VIN: **2C3CDXBG3LH100442**
Work Order/
Stock Number: **46394393**
Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**
Client Stock #: **G10B2420**
Vehicle Grade : **Grade 3.7**
Remarks: **-**
Announcements:

**• Prior Law
Enforcement**

Certification : **-**
Req. Prev. Repair **-**
Order: **-**



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	Yes
Engine:	6-Cylinder Flex Fuel	Cruise Control:	Yes
Engine Size:	3.6 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	AM Radio	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /BLACK	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Buckets	Drive Type:	Rear Wheel Drive
Seat Count:	-	Brakes:	Disc

Equipment

Additional Equipment:

Car Tire Size - LF 215 / 65 R 17

Car Tire Size - LR 215 / 65 R 17

Car Tire Size - RR 215 / 65 R 17

Car Tire Size - RF 215 / 65 R 17

LF Tires - 8/32 inch

LR Tires - 8/32 inch

RF Tires - 8/32 inch

RR Tires - 7/32 inch

Tire Brand - Front Left - FIRESTONE

Tire Brand - Front Right - FIRESTONE

Tire Brand - Rear Left - FIRESTONE

Tire Brand - Rear Right - FIRESTONE

Tire Model - RR - Firehawk As V2

Tire Model - RF - Firehawk As V2

Tire Model - LR - Firehawk As V2

Tire Model - LF - Firehawk As V2

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Odometer	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Steering Wheel	Worn	-	Acceptable
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Rear Seats	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Front Bumper	Bug Damage	-	Repair Required
	Hood	Chipped	-	3
	Right Front Wheel	Curb Rash	-	2 To 3 Inches
	Right Rear Wheel	Curb Rash	-	1/2 To 1 Inch
	Left Qtr Panel	Multiple Scratches Light	-	3
	Left Rear Wheel	Curb Rash	-	1/2 To 1 Inch

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Left Rear Door	Chipped	-	2
	Left Front Door	Multiple Scratches Heavy	-	3

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.