Approved CR

IAA Savannah
348 Commerce Dr.
Branch No 704
Rincon, GA 31326
(912) 826-1219/(912) 826-1387
WHOLESALE ASSESSMENT ONLY

Make/Model:	**2017 CHEVROLET EXPRESS 3500**
Bodystyle/Series:	**- LT**
Color:	**Silver**
Mileage:	**89,327 (Verified)**
Turn-in Mileage:	-
VIN:	**1GAZGPFG6H1268582**
Work Order/ Stock Number:	**45964847**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G431237U**
Vehicle Grade :	**Grade 3.7**
Remarks:	-
Announcements:	-
Certification :	-
Req. Prev. Repair Order:	-



Drivable: Yes

Equipment

Transmission:	**Automatic Transmission**	A/C:	**No**
Engine:	**8-Cylinder Flex Fuel**	Cruise Control:	**Yes**
Engine Size:	**6 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**Yes**
Radio:	-	Pwr Windows	**Yes**
Interior - Type/Color:	**Cloth/Vinyl /GRAY**	Rear Defroster:	**No**
Airbag:	**Driver Side Air Bag**	Tilt Steering:	**Yes**
Seats:	**5th**	Drive Type:	**Rear Wheel Drive**
Seat Count:	-	Brakes:	**Air Brakes**

Equipment

Additional Equipment:

Car Tire Size - RR 245 / 75 R 16	Car Tire Size - RF 245 / 75 R 16	Car Tire Size - LF 245 / 75 R 16
Car Tire Size - LR 245 / 75 R 16	LF Tires - 8/32 inch	LR Tires - 8/32 inch
RF Tires - 8/32 inch	RR Tires - 8/32 inch	Tire Brand - Front Left - FIRESTONE
Tire Brand - Front Right - FIRESTONE	Tire Brand - Rear Left - GENERAL	Tire Brand - Rear Right - GENERAL
Tire Model - LF - Transforce HT	Tire Model - LR - Grabber	Tire Model - RF - Transforce HT
Tire Model - RR - Grabber		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Seats	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-
	Extra Photo 6	Photo Only	-	-
	Extra Photo 7	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	4th Row Seat	Missing	-	Replacement Required
	Left Head Lamp	Faded	-	Acceptable
	Right Head Lamp	Faded	-	Acceptable

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.