



Approved CR

IAA Albuquerque  
4400 Broadway Blvd SE  
Branch No 140  
Albuquerque, NM 87105  
(505) 873-2081/(505) 873-3029  
WHOLESALE ASSESSMENT ONLY

Make/Model: **2017  
CHEVROLET  
SILVERADO  
2500HD**

Bodystyle/Series: **Crew Cab  
WT**

Color: **Black**

Mileage: **37,228  
(Verified)**

Turn-in Mileage: **-**

VIN: **1GC1KUEG6HF203897**

Work Order/  
Stock Number: **46332342**

Customer: **GSA Fleet Vehicle Sales  
1800 F Street NW  
Washington, DC 20405  
fleetsalesupport@gsa.gov**

Client Stock #: **G63-1989U**

Vehicle Grade : **Grade 2.4**

Remarks: **-**

Announcements: **-**

Certification : **-**

Req. Prev. Repair **-**

Order: **-**



Drivable: Yes

### Equipment

|                        |                               |                 |                      |
|------------------------|-------------------------------|-----------------|----------------------|
| Transmission:          | <b>Automatic Transmission</b> | A/C:            | <b>No</b>            |
| Engine:                | <b>8-Cylinder Flex Fuel</b>   | Cruise Control: | <b>Yes</b>           |
| Engine Size:           | <b>6 L</b>                    | Pwr Steering:   | <b>Yes</b>           |
| Roof:                  | <b>Hard Top</b>               | Pwr Locks:      | <b>Yes</b>           |
| Radio:                 | <b>-</b>                      | Pwr Windows     | <b>Yes</b>           |
| Interior - Type/Color: | <b>Cloth Interior /GRAY</b>   | Rear Defroster: | <b>No</b>            |
| Airbag:                | <b>Driver Side Air Bag</b>    | Tilt Steering:  | <b>Yes</b>           |
| Seats:                 | <b>3rd</b>                    | Drive Type:     | <b>4-Wheel Drive</b> |
| Seat Count:            | <b>-</b>                      | Brakes:         | <b>Disc</b>          |

## Equipment

### Additional Equipment:

Car Tire Size - LF 245 / 75 R 17

Car Tire Size - LR 245 / 75 R 17

Car Tire Size - RR 245 / 75 R 17

Car Tire Size - RF 245 / 75 R 17

LF Tires - 8/32 inch

LR Tires - 12/32 inch

RF Tires - 8/32 inch

RR Tires - 3/32 inch

Tire Brand - Front Left - FIRESTONE

Tire Brand - Front Right - FIRESTONE

Tire Brand - Rear Left - FIRESTONE

Tire Brand - Rear Right - FIRESTONE

Tire Model - RR - Destination X/T


Tire Model - RF - Destination X/T

Tire Model - LR - Destination X/T

Tire Model - LF - Destination X/T

## Non Chargeable Damages

| Photo                                                                               | Item                   | Damage     | Action | Severity        |
|-------------------------------------------------------------------------------------|------------------------|------------|--------|-----------------|
|    | Rear Seats             | Photo Only | -      | -               |
|   | Right Rear Wheel       | Rust       | -      | Repair Required |
|  | Photo - Vin/Id Sticker | Photo Only | -      | -               |
|  | Engine                 | Photo Only | -      | -               |
|  | Keys                   | Photo Only | -      | -               |
|  | Front Cover Center     | Photo Only | -      | -               |
|  | Right Side Panel       | Photo Only | -      | -               |

| Non Chargeable Damages                                                              |                         |            |        |          |
|-------------------------------------------------------------------------------------|-------------------------|------------|--------|----------|
| Photo                                                                               | Item                    | Damage     | Action | Severity |
|    | Left Side Panel         | Photo Only | -      | -        |
|    | Instrument Panel        | Photo Only | -      | -        |
|    | Rear Bumper             | Photo Only | -      | -        |
|    | Extra Photo 2           | Photo Only | -      | -        |
|    | Right Front Fender      | Photo Only | -      | -        |
|   | Left Front Fender       | Photo Only | -      | -        |
|  | Left Rear Bumper/Cover  | Photo Only | -      | -        |
|  | Right Rear Bumper/Cover | Photo Only | -      | -        |
|  | Photo - Dash            | Photo Only | -      | -        |
|  | Extra Photo 1           | Photo Only | -      | -        |
|  | Odometer                | Photo Only | -      | -        |

### Non Chargeable Damages

| Photo                                                                             | Item     | Damage      | Action | Severity   |
|-----------------------------------------------------------------------------------|----------|-------------|--------|------------|
|  | Tailgate | Aftermarket | -      | Acceptable |

### Chargeable Damages

| Photo                                                                                                                                                                                                                                                                       | Item                      | Damage                 | Action | Severity             |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------|------------------------|--------|----------------------|
|  | Right Rear Tire           | Worn                   | -      | Replacement Required |
|                                                                                                                                                                                           | Tailgate                  | Rust                   | -      | > 12 Inches          |
|                                                                                                                                                                                          | Right Bed Side            | Dent(S) W/ Paint Dmg   | -      | > 12 Inches          |
|                                                                                                                                                                                          | Front Metal Bumper Chrome | Dent(S) W/No Paint Dmg | -      | > 12 Inches          |
|                                                                                                                                                                                          | Front Bumper Cover Lower  | Dent(S) W/No Paint Dmg | -      | > 12 Inches          |

### Chargeable Damages

| Photo                                                                             | Item                    | Damage                   | Action | Severity    |
|-----------------------------------------------------------------------------------|-------------------------|--------------------------|--------|-------------|
|  | Right Rear Door Panel   | Heavy Scratch            | -      | > 12 Inches |
|  | Left Rear Door Panel    | Multiple Scratches Heavy | -      | 10 Or More  |
|  | Left Front Seat Cushion | Cut                      | -      | < 1/8 Inch  |

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.