



Approved CR

IAA Albuquerque
4400 Broadway Blvd SE
Branch No 140
Albuquerque, NM 87105
(505) 873-2081/(505) 873-3029
WHOLESALE ASSESSMENT ONLY

Make/Model: **2017 FORD EXPLORER**
Bodystyle/Series: **Sport Utility Vehicle -**
Color: **Silver**
Mileage: **18,281 (Verified)**
Turn-in Mileage: **-**
VIN: **1FM5K8B82HGC91911**
Work Order/
Stock Number: **46332183**
Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**
Client Stock #: **G62-2188U**
Vehicle Grade : **Grade 3.7**
Remarks: **-**
Announcements: **-**
Certification : **-**
Req. Prev. Repair **-**
Order: **-**



Drivable: Yes

Equipment


Transmission:	Automatic Transmission	A/C:	No
Engine:	6-Cylinder Gas	Cruise Control:	Yes
Engine Size:	3.5 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /-	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	3rd	Drive Type:	4-Wheel Drive
Seat Count:	-	Brakes:	Disc

Equipment


Additional Equipment:

Car Tire Size - LF 245 / 60 R 18	Car Tire Size - LR 245 / 60 R 18	Car Tire Size - RR 245 / 60 R 18
Car Tire Size - RF 245 / 60 R 18	LF Tires - 4/32 inch	LR Tires - 6/32 inch
RF Tires - 3/32 inch	RR Tires - 6/32 inch	Tire Brand - Front Left - MICHELIN
Tire Brand - Front Right - MICHELIN	Tire Brand - Rear Left - MICHELIN	Tire Brand - Rear Right - MICHELIN
Tire Model - RR - Latitude Tour HP	Tire Model - RF - Latitude Tour HP	Tire Model - LR - Latitude Tour HP
Tire Model - LF - Latitude Tour HP		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Front Fender	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Keys	Photo Only	-	-
	Engine	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Vin/Id Sticker	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Odometer	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Bumper	Heavy Scratch	-	1 To 2 Inches

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Right Front Tire	Worn	-	Replacement Required
	Left Rear Door	Dent(S) W/ Paint Dmg	-	2 To 3 Inches
	Right Head Lamp	Faded	-	Repair Required
	Left Head Lamp	Faded	-	Repair Required

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.