



Approved CR

IAA Las Vegas
3225 South Hollywood Blvd
Branch No 152
Las Vegas, NV 89122
(702) 565-8795/(702) 564-6553
WHOLESALE ASSESSMENT ONLY

Make/Model: **2012 FORD
F-450
CHASSIS**
Bodystyle/Series: **Extended Cab
XL**
Color: **White**
Mileage: **34,325
(Verified)**
Turn-in Mileage: **-**
VIN: **1FD9X4HY6CEC73306**
Work Order/
Stock Number: **46308448**
Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**
Client Stock #: **G710056Y**
Vehicle Grade : **Grade 3.5**
Remarks: **-**
Announcements: **-**
Certification : **-**
Req. Prev. Repair **-**
Order: **-**



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	10-Cylinder Gas	Cruise Control:	No
Engine Size:	6.8 L	Pwr Steering:	Yes
Roof:	Carriage	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Leather Interior /GRAY	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	5th	Drive Type:	4-Wheel Drive
Seat Count:	-	Brakes:	Air Brakes

Equipment

Additional Equipment:

Car Tire Size - LF 225 / 70 R 19.5

Car Tire Size - LR 225 / 70 R 19.5

Car Tire Size - RR 225 / 70 R 19.5

Car Tire Size - RF 225 / 70 R 19.5

LF Tires - 9/32 inch

LR Tires - 11/32 inch

RF Tires - 9/32 inch

RR Tires - 11/32 inch

Tire Brand - Front Left - BFGOODRICH

Tire Brand - Front Right - BFGOODRICH

Tire Brand - Rear Left - MICHELIN

Tire Brand - Rear Right - MICHELIN

Tire Model - RR - Xze

Tire Model - RF - ST230

Tire Model - LR - Xze

Tire Model - LF - ST230

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Seats	Photo Only	-	-
	Odometer	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Front Fender	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Keys	Photo Only	-	-
	Engine	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Pickup Bed	Aftermarket	-	Acceptable

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Front Wheel	Rust	-	Repair Required
	Rear Metal Bumper Painted	Rust	-	> 12 Inches
	Left Rocker Panel	Heavy Scratch	-	8 To 9 Inches

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.