



Approved CR

IAA Anchorage
1446 W Mystery Ave
Branch No 372
Wasilla, AK 99654
(907)312-5580/(907)312-5680
WHOLESALE ASSESSMENT ONLY

Make/Model: **2016
CHEVROLET
SILVERADO
3500HD
CHASSIS**

Bodystyle/Series: **- LT**

Color: **White**

Mileage: **37,199
(Verified)**

Turn-in Mileage: **-**

VIN: **1GB3KZC80GF180685**

Work Order/
Stock Number: **46319137**

Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**

Client Stock #: **G310148S**

Vehicle Grade : **Grade 2.1**

Remarks: **-**

Announcements: **-**

Certification : **-**

Req. Prev. Repair **-**

Order: **-**



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	8-Cylinder Diesel	Cruise Control:	Yes
Engine Size:	6.6 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /BLACK	Rear Defroster:	No
Airbag:	Driver Side Air Bag	Tilt Steering:	No
Seats:	3rd	Drive Type:	4-Wheel Drive
Seat Count:	-	Brakes:	Hydraulic Brakes

Equipment

Additional Equipment:

Car Tire Size - LF 235 / 80 R 17

Car Tire Size - LR 235 / 80 R 17

Car Tire Size - RR 235 / 80 R 17

Car Tire Size - RF 235 / 80 R 17

LF Tires - 7/32 inch

LR Tires - 7/32 inch

RF Tires - 7/32 inch

RR Tires - 8/32 inch

Tire Brand - Front Left - TOYO

Tire Brand - Front Right - TOYO

Tire Brand - Rear Left - TOYO

Tire Brand - Rear Right - TOYO

Tire Model - RR - Observe Open Country
G-02 Plus

Tire Model - RF - Observe Open Country
G-02 Plus

Tire Model - LR - Observe Open Country
G-02 Plus

Tire Model - LF - Observe Open Country
G-02 Plus

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Cargo Box	Aftermarket	-	Acceptable
	Left Rear Rail	Previous Repair	-	Acceptable
	Right Rear Rail	Previous Repair	-	Acceptable
	Center Console	Aftermarket	-	Acceptable

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Cargo Shelf	Aftermarket	-	Acceptable
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Front Metal Bumper Chrome	Multiple Dents/No Paint Damage	-	2
	Overall Vehicle	De-Identify	-	Removal Required

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Front Wheel	Curb Rash	-	5 To 6 Inches
	Right Rear Wheel	Curb Rash	-	6 To 7 Inches
	Left Rear Wheel	Curb Rash	-	5 To 6 Inches
	Left Front Fender	Chipped	-	2
	Left Front Wheel	Curb Rash	-	9 To 10 Inches

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.