Approved CR

Dealers Auto Auction of Mobile
3030 McVay Drive North
Mobile, AL 36606
2513387653
WHOLESALE ASSESSMENT ONLY



Make/Model:	**2015 FORD F-350 CHASSIS**
Bodystyle/Series:	**2 Door Vehicle XL REG CAB C/C 2WD DRW**
Color:	**WHITE**
Mileage:	**4,806 (Verified, 6 digits)**
Turn-in Mileage:	-
VIN:	**1FDRF3G60FED11100**
Work Order/ Stock Number:	**000593619**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**430402R**
Vehicle Grade :	**Grade 3.1**
AutoGrade :	**3.1 - Average**
Remarks:	-
Announcements:	-
Certification :	**Not Certified**
Req. Prev. Repair Order:	-

Drivable: Yes

UniBody/Frame Damage: NO As Is 100K Miles: NO

Equipment

Transmission:	**Automatic Transmission**	A/C:	**No**
Engine:	**8-Cylinder Gas**	Cruise Control:	**No**
Engine Size:	**6.2 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**Yes**
Radio:	**AM/FM CD**	Pwr Windows	**No**
Interior - Type/Color:	**Vinyl Interior /GRAY**	Rear Defroster:	**No**
Airbag:	**Dual Air Bags**	Tilt Steering:	**Yes**
Seats:	-	Drive Type:	**Rear Wheel Drive**
Seat Count:	-	Brakes:	**Power Brakes**

Equipment


Additional Equipment:

ABS Brakes	Auxiliary Pwr Outlet	Bench Seating
CD Player	Car Tire Size - LR tire size LT245/75SR17	Car Tire Size - RR tire size LT245/75SR17
Car Tire Size - RF tire size LT245/75SR17	Car Tire Size - LF tire size LT245/75SR17	Car Tire Size - Hood
Cylinders - 8	Daytime Running Lights	Driver Air Bag
Dual Rear Wheels	Empty Weight - 6010 lb	Intermittent Wipers
LF Tires - 9/32 inch	LR Tires - 9/32 inch	MP3 Radio
Master Key - 2key(s)	Motor Fuel Type - Gas	Pass. Air Bag
Power Brakes	Power Lock	Power Steering
Privacy Glass	RF Tires - 9/32 inch	RR Tires - 9/32 inch
Rear View Mirror	Seat Trim - Vinyl	Side Airbags - Front
Tilt Steering Wheel	Tilt Wheel	Tire Brand - Front Left - L qtr panel
Tire Brand - Front Left - LF tire mfg General	Tire Brand - Front Right - RF tire mfg General	Tire Brand - Rear Left - LR tire mfg General
Tire Brand - Rear Right - RR tire mfg General	Traction Control	Transmission - Automatic Transmission w/ Overdrive
Two-Wheel Drive	Wheels Front Left - Steel	Wheels Front Right - Steel
Wheels Rear Left - Steel	Wheels Rear Right - Steel	

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Vin/Id Sticker	Photo Only	Estimate Only	Unknown
	Steering Wheel	Photo Only	Estimate Only	Unknown
	Stereo	Photo Only	Estimate Only	Unknown
	Roof	Photo Only	Estimate Only	Unknown
	Keys	Photo Only	Estimate Only	Unknown

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Door Panels	Photo Only	Estimate Only	Unknown
	Left Front Tire	Photo Only	Estimate Only	Unknown
	Right Front Tire	Photo Only	Estimate Only	Unknown
	Right Rear Tire	Photo Only	Estimate Only	Unknown
	Photo - Rear	Photo Only	Estimate Only	Unknown
	Left Rear Tire	Photo Only	Estimate Only	Unknown
	Deck Lid Badge	Photo Only	Estimate Only	Unknown
	Trunk	Photo Only	Estimate Only	Unknown
	Left Front Fender	Photo Only	Estimate Only	Unknown
	Right Front Fender	Photo Only	Estimate Only	Unknown
	Right Qtr Panel	Photo Only	Estimate Only	Unknown
	Left Qtr Panel	Photo Only	Estimate Only	Unknown

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Hood	Photo Only	Estimate Only	Unknown
	Extra Photo 2	Photo Only	Estimate Only	Unknown
	Extra Photo 1	Photo Only	Estimate Only	Unknown
	Overall Picture - Odometer	Photo Only	Estimate Only	Unknown
	Photo - Wheel	Photo Only	Estimate Only	Unknown
	Photo - Front	Photo Only	Estimate Only	Unknown
	Photo - Interior	Photo Only	Estimate Only	Unknown
	Photo - Dash	Photo Only	Estimate Only	Unknown
	Overall Picture - Engine	Photo Only	Estimate Only	Unknown
	Extra Photo 3	Photo Only	Estimate Only	Unknown

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Front Bumper	Enviro Paint Damage	Refinish	> 12 Inches
	Hood	Chipped	Repair	7

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Bed Side	Multiple Scratches Heavy	Repair	8
	Lift Gate	Chipped	Repair	8
	Left Front Fender	Multiple Scratches Heavy	Repair	5
	Right Bed Side	Multiple Scratches Heavy	Repair	8
	Rear Bumper	Chipped	Repair	5
	Warning Light - Engine	On	Report	Unacceptable
[no photo]	Right Front Door	Multiple Scratches Heavy	Repair	5
[no photo]	Left Front Door	Chipped	Repair	5

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.