Approved CR

IAA Austin North
23010 Firefly Rd
Branch No 457
Florence, TX 76527
2549700575
mgr-austinnorth@iaai.com
WHOLESALE ASSESSMENT ONLY



| | |
|---|---|
| Make/Model: | **2019 DODGE CHARGER** |
| Bodystyle/Series: | **4 Door Sedan POLICE RWD** |
| Color: | **Black** |
| Mileage: | **63,597 (Verified)** |
| Turn-in Mileage: | - |
| VIN: | **2C3CDXAG9KH741899** |
| Work Order/ Stock Number: | **46445457** |
| Customer: | GSA Fleet Vehicle Sales<br>1800 F Street NW<br>Washington, DC 20405<br>fleetsalessupport@gsa.gov |
| Client Stock #: | - |
| Vehicle Grade : | **Grade 2.7** |
| Remarks: | - |
| Announcements: | - |
| Certification : | - |
| Req. Prev. Repair Order: | - |

Drivable: Yes

## Equipment

| | | | |
|---|---|---|---|
| Transmission: | **Automatic Transmission** | A/C: | **No** |
| Engine: | **6-Cylinder Flex Fuel** | Cruise Control: | **Yes** |
| Engine Size: | **3.6 L** | Pwr Steering: | **Yes** |
| Roof: | **Hard Top** | Pwr Locks: | **Yes** |
| Radio: | - | Pwr Windows | **Yes** |
| Interior - Type/Color: | **Cloth Interior /BLACK** | Rear Defroster: | **Yes** |
| Airbag: | **Driver Side Air Bag** | Tilt Steering: | **Yes** |
| Seats: | **4th** | Drive Type: | **Rear Wheel Drive** |
| Seat Count: | - | Brakes: | **Disc** |

## Equipment

Additional Equipment:

| | | |
|---|---|---|
| Car Tire Size - LF 225 / 60 R 18 | Car Tire Size - LR 225 / 60 R 18 | Car Tire Size - RR 225 / 60 R 18 |
| Car Tire Size - RF 225 / 60 R 18 | LF Tires - 8/32 inch | LR Tires - 8/32 inch |
| RF Tires - 8/32 inch | RR Tires - 8/32 inch | Tire Brand - Front Left - FALKEN |
| Tire Brand - Front Right - FALKEN | Tire Brand - Rear Left - FALKEN | Tire Brand - Rear Right - FALKEN |
| Tire Model - RR - Pro G5 CSV | Tire Model - RF - Pro G5 CSV | Tire Model - LR - Pro G5 CSV |
| Tire Model - LF - Pro G5 CSV | | |

## Non Chargeable Damages

| Photo | Item | Damage | Action | Severity |
|---|---|---|---|---|
|  | Keys | Photo Only | - | - |
|  | Front Cover Center | Photo Only | - | - |
|  | Right Side Panel | Photo Only | - | - |
|  | Left Side Panel | Photo Only | - | - |
|  | Instrument Panel | Photo Only | - | - |
|  | Rear Bumper | Photo Only | - | - |
|  | Right Front Fender | Photo Only | - | - |
|  | Left Front Fender | Photo Only | - | - |

## Non Chargeable Damages

| Photo | Item | Damage | Action | Severity |
|---|---|---|---|---|
|  | Left Rear Bumper/Cover | Photo Only | - | - |
|  | Right Rear Bumper/Cover | Photo Only | - | - |
|  | Photo - Dash | Photo Only | - | - |
|  | Extra Photo 1 | Photo Only | - | - |
|  | Odometer | Photo Only | - | - |
|  | Rear Seats | Photo Only | - | - |
|  | Engine | Photo Only | - | - |
|  | Photo - Vin/Id Sticker | Photo Only | - | - |
|  | Cargo Shelf | Aftermarket | - | Acceptable |

## Chargeable Damages

| Photo | Item | Damage | Action | Severity |
|---|---|---|---|---|
|  | Right Front Wheel Cover | Curb Rash | - | 1 To 2 Inches |
|  | Left Front Door | Chipped | - | 2 |
|  | Deck Lid | Multiple Dents/No Paint Damage | - | 4 |
|  | Left Drip Rail | Multiple Dents/No Paint Damage | - | 4 |
|  | Roof | Hail Damage | - | 10 Or More |
|  | Front Bumper | Bug Damage | - | Repair Required |

## Chargeable Damages

| Photo | Item | Damage | Action | Severity |
|---|---|---|---|---|
|  | Hood | Multiple Dents/Paint Damage | - | 2 |

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.