



Approved CR

IAA North Virginia
15 Le Way Drive
Branch No 723
Fredericksburg, VA 22406
(540) 373-7800/(540) 371-4123
WHOLESALE ASSESSMENT ONLY

Make/Model: **2015 FORD
F-450
CHASSIS**

Bodystyle/Series: **Crew Cab XL**

Color: **Navy**

Mileage: **57,783
(Verified)**

Turn-in Mileage: **-**

VIN: **1FD9W4HT3FEB05389**

Work Order/
Stock Number: **46423709**

Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**

Client Stock #: **G710425Z**

Vehicle Grade : **Grade 2.8**

Remarks: **-**

Announcements: **• Rust**

Certification : **-**

Req. Prev. Repair **-**

Order: **-**



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	Yes
Engine:	8-Cylinder Diesel	Cruise Control:	Yes
Engine Size:	6.7 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /GRAY	Rear Defroster:	No
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Buckets	Drive Type:	4-Wheel Drive
Seat Count:	-	Brakes:	Disc

Equipment

Additional Equipment:

Car Tire Size - RR 225 / 70 R 19.5	Car Tire Size - RF 225 / 70 R 19.5	Car Tire Size - LF 225 / 70 R 19.5
Car Tire Size - LR 225 / 70 R 19.5	LF Tires - 13/32 inch	LR Tires - 13/32 inch
RF Tires - 13/32 inch	RR Tires - 13/32 inch	Tire Brand - Front Left - HERCULES
Tire Brand - Front Right - HERCULES	Tire Brand - Rear Left - HERCULES	Tire Brand - Rear Right - HERCULES
Tire Model - LF - Strong Guard H-Ra	Tire Model - RF - Strong Guard H-Ra	Tire Model - RR - Strong Guard H-Ra
Tire Model - LR - Strong Guard H-Ra		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Front Metal Bumper Painted	Aftermarket	-	Acceptable
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Left Rear Door	Multiple Scratches Heavy	-	2
	Right Cab Side	Multiple Scratches Heavy	-	10 Or More
	Right Front Door	Chipped	-	5
	Left Head Lamp	Faded	-	Repair Required
	Right Head Lamp	Faded	-	Repair Required
	Front Metal Bumper Painted	Heavy Scratch	-	> 12 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Front Wheel	Rust	-	Repair Required
	Right Rear Wheel	Rust	-	Repair Required
	Left Rear Wheel	Rust	-	Repair Required
	Left Front Wheel	Rust	-	Repair Required
	Right Front Seat Back	Hole(S)	-	< 1/8 Inch
	Left Front Seat Back	Hole(S)	-	< 1/8 Inch

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Steering Wheel	Worn	-	Replacement Required

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.