



Approved CR

IAA Chicago South  
16425 S Crawford Ave  
Branch No 515  
Markham, IL 60426  
(708) 333-5700/(708) 333-5756  
WHOLESALE ASSESSMENT ONLY

Make/Model: **2018  
HYUNDAI  
IONIQ  
HYBRID**

Bodystyle/Series: **4 Door Hatch  
Back BLUE**

Color: **Black**

Mileage: **57,266  
(Verified)**

Turn-in Mileage: **-**

VIN: **KMHC65LC0JU076225**

Work Order/  
Stock Number: **46400539**

Customer: **GSA Fleet Vehicle Sales  
1800 F Street NW  
Washington, DC 20405  
fleetsalessupport@gsa.gov**

Client Stock #: **G133128V**

Vehicle Grade : **Grade 3.6**

Remarks: **-**

Announcements: **-**

Certification : **-**

Req. Prev. Repair **-**

Order: **-**



Drivable: Yes

### Equipment

|                        |                      |                 |                   |
|------------------------|----------------------|-----------------|-------------------|
| Transmission:          | -                    | A/C:            | No                |
| Engine:                | 4-Cylinder Hybrid    | Cruise Control: | Yes               |
| Engine Size:           | 1.6 L                | Pwr Steering:   | Yes               |
| Roof:                  | Coach                | Pwr Locks:      | Yes               |
| Radio:                 | -                    | Pwr Windows     | Yes               |
| Interior - Type/Color: | Cloth Interior /GRAY | Rear Defroster: | Yes               |
| Airbag:                | Driver Side Air Bag  | Tilt Steering:  | Yes               |
| Seats:                 | 3rd                  | Drive Type:     | Front Wheel Drive |
| Seat Count:            | -                    | Brakes:         | Anti Lock Brakes  |

## Equipment

### Additional Equipment:

Car Tire Size - RR 195 / 65 R 15

Car Tire Size - RF 195 / 65 R 15

Car Tire Size - LF 195 / 65 R 15

Car Tire Size - LR 195 / 65 R 15

LF Tires - 7/32 inch

LR Tires - 7/32 inch

RF Tires - 8/32 inch

RR Tires - 7/32 inch

Tire Brand - Front Left - KUMHO

Tire Brand - Front Right - KUMHO

Tire Brand - Rear Left - KUMHO

Tire Brand - Rear Right - KUMHO

Tire Model - LF - Solus TA31

Tire Model - LR - Solus TA31


Tire Model - RF - Solus TA31

Tire Model - RR - Solus TA31

## Non Chargeable Damages

| Photo                                                                               | Item                   | Damage     | Action | Severity |
|-------------------------------------------------------------------------------------|------------------------|------------|--------|----------|
|    | Rear Seats             | Photo Only | -      | -        |
|    | Photo - Vin/Id Sticker | Photo Only | -      | -        |
|   | Engine                 | Photo Only | -      | -        |
|  | Keys                   | Photo Only | -      | -        |
|  | Front Cover Center     | Photo Only | -      | -        |
|  | Right Side Panel       | Photo Only | -      | -        |
|  | Left Side Panel        | Photo Only | -      | -        |
|  | Instrument Panel       | Photo Only | -      | -        |

### Non Chargeable Damages

| Photo                                                                               | Item                    | Damage     | Action | Severity |
|-------------------------------------------------------------------------------------|-------------------------|------------|--------|----------|
|    | Rear Bumper             | Photo Only | -      | -        |
|    | Extra Photo 2           | Photo Only | -      | -        |
|    | Extra Photo 3           | Photo Only | -      | -        |
|    | Right Front Fender      | Photo Only | -      | -        |
|    | Extra Photo 4           | Photo Only | -      | -        |
|   | Extra Photo 5           | Photo Only | -      | -        |
|  | Left Front Fender       | Photo Only | -      | -        |
|  | Left Rear Bumper/Cover  | Photo Only | -      | -        |
|  | Right Rear Bumper/Cover | Photo Only | -      | -        |
|  | Photo - Dash            | Photo Only | -      | -        |
|  | Extra Photo 1           | Photo Only | -      | -        |

### Non Chargeable Damages

| Photo                                                                             | Item     | Damage     | Action | Severity |
|-----------------------------------------------------------------------------------|----------|------------|--------|----------|
|  | Odometer | Photo Only | -      | -        |

### Chargeable Damages

| Photo                                                                               | Item               | Damage  | Action | Severity        |
|-------------------------------------------------------------------------------------|--------------------|---------|--------|-----------------|
|    | Hood               | Chipped | -      | 3               |
|    | Right Head Lamp    | Faded   | -      | Repair Required |
|   | Front Bumper       | Scraped | -      | 2 To 3 Inches   |
|  | Right Front Fender | Chipped | -      | 2               |
|  | Right Qtr Panel    | Chipped | -      | 2               |

### Chargeable Damages

| Photo                                                                               | Item                   | Damage    | Action | Severity      |
|-------------------------------------------------------------------------------------|------------------------|-----------|--------|---------------|
|    | Right Rear Wheel Cover | Curb Rash | -      | 2 To 3 Inches |
|    | Left Rear Door         | Chipped   | -      | 2             |
|    | Left Rear Wheel Cover  | Peeling   | -      | 2 To 3 Inches |
|   | Left Rocker Panel      | Chipped   | -      | 2             |
|  | Left Front Wheel Cover | Curb Rash | -      | 7 To 8 Inches |
|  | Roof                   | Chipped   | -      | 3             |

| Chargeable Damages                                                                |                |                          |        |                 |
|-----------------------------------------------------------------------------------|----------------|--------------------------|--------|-----------------|
| Photo                                                                             | Item           | Damage                   | Action | Severity        |
|  | Grille         | Peeling                  | -      | > 12 Inches     |
|  | Rear Bumper    | Multiple Scratches Heavy | -      | 4               |
|  | Left Head Lamp | Faded                    | -      | Repair Required |

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.