



Approved
CR

IAA Burlington
304 Colchester Road
Branch No 645
Essex, VT 05451
(802) 872-7838/(802) 878-8353
WHOLESALE ASSESSMENT ONLY

Make/Model: **2018 FORD F-150**
Bodystyle/Series: **- XL**
Color: **White**
Mileage: **49,354 (Verified)**
Turn-in Mileage: **-**
VIN: **1FTMF1CBXJKE82825**
Work Order/
Stock Number: **46400734**
Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalessupport@gsa.gov**
Client Stock #: **G420267U**
Vehicle Grade : **Grade 3.9**
Remarks: **-**
Announcements: **• ANNOUNCEMENTS:**
Certification : **-**
Req. Prev. Repair **-**
Order:



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	6-Cylinder Gas	Cruise Control:	Yes
Engine Size:	3.3 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /BLACK	Rear Defroster:	No
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Bench	Drive Type:	Rear Wheel Drive
Seat Count:	-	Brakes:	Disc

Equipment

Additional Equipment:

Car Tire Size - LF 245 / 70 R 17	Car Tire Size - LR 245 / 70 R 17	Car Tire Size - RR 245 / 70 R 17
Car Tire Size - RF 245 / 70 R 17	LF Tires - 8/32 inch	LR Tires - 8/32 inch
RF Tires - 8/32 inch	RR Tires - 8/32 inch	Tire Brand - Front Left - GOODYEAR
Tire Brand - Front Right - GOODYEAR	Tire Brand - Rear Left - GOODYEAR	Tire Brand - Rear Right - GOODYEAR
Tire Model - RR - Wrangler At	Tire Model - RF - Wrangler At	Tire Model - LR - Wrangler At
Tire Model - LF - Wrangler At		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-

Non Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Keys	Photo Only	-	-

Chargeable Damages				
Photo	Item	Damage	Action	Severity

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Right Front Wheel	Peeling	-	> 12 Inches
	Right Rear Wheel	Peeling	-	> 12 Inches
	Tailgate	Heavy Scratch	-	1/2 To 1 Inch
	Left Rear Wheel	Peeling	-	> 12 Inches
	Left Front Wheel	Peeling	-	> 12 Inches

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.