Approved CR

IAA Louisville North
891 Ballardsville Road
Branch No 669
Eminence, KY 40019
(502) 215-4804
WHOLESALE ASSESSMENT ONLY

Make/Model:	**2019 HYUNDAI ELANTRA**
Bodystyle/Series:	**4 Door Sedan SE**
Color:	**Blue**
Mileage:	**129,156 (Verified)**
Turn-in Mileage:	-
VIN:	**5NPD74LF9KH497608**
Work Order/ Stock Number:	**46502969**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G130274W**
Vehicle Grade :	**Grade 2.2**
Remarks:	-
Announcements:	• HAIL DAMAGE
Certification :	-
Req. Prev. Repair Order:	-



Drivable: Yes

Equipment

Transmission:	**Automatic Transmission**	A/C:	**No**
Engine:	**4-Cylinder Gas**	Cruise Control:	**Yes**
Engine Size:	**2 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**Yes**
Radio:	-	Pwr Windows	**Yes**
Interior - Type/Color:	**Cloth Interior /GRAY**	Rear Defroster:	**Yes**
Airbag:	**Driver Side Air Bag**	Tilt Steering:	**Yes**
Seats:	**Buckets**	Drive Type:	**Front Wheel Drive**
Seat Count:	-	Brakes:	**Disc**

Equipment


Additional Equipment:

Car Tire Size - LF 195 / 65 R 15	Car Tire Size - LR 195 / 65 R 15	Car Tire Size - RR 195 / 65 R 15
Car Tire Size - RF 195 / 65 R 15	LF Tires - 6/32 inch	LR Tires - 7/32 inch
RF Tires - 5/32 inch	RR Tires - 6/32 inch	Tire Brand - Front Left - MILESTAR
Tire Brand - Front Right - KUMHO	Tire Brand - Rear Left - KUMHO	Tire Brand - Rear Right - KUMHO
Tire Model - RR - Solus TA51A	Tire Model - RF - Solus TA51A	Tire Model - LR - Solus TA51A
Tire Model - LF - MS932 Sport		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Door Handle (Interior)	Worn	-	Replacement Required
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-
	Extra Photo 6	Photo Only	-	-
	Left Front Fender	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Warning - Tire Pressure	On	-	Unacceptable

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Hood	Hail Damage	-	10 Or More
	Right Rocker Panel	Dent(S) W/ Paint Dmg	-	1 To 2 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Front Bumper	Bug Damage	-	Repair Required
	Right Front Wheel	Corrosion	-	> 12 Inches
	Right Front Wheel Cover	Curb Rash	-	2 To 3 Inches
	Right Rear Wheel	Corrosion	-	> 12 Inches
	Deck Lid	Multiple Dents/No Paint Damage	-	2
	Left Rear Door	Multiple Scratches Heavy	-	3

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Rear Wheel	Corrosion	-	> 12 Inches
	Left Front Wheel	Corrosion	-	> 12 Inches
	Left Front Wheel Cover	Curb Rash	-	2 To 3 Inches
	Roof	Hail Damage	-	10 Or More
	Left Qtr Panel	Multiple Scratches Light	-	2

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.