Approved CR

IAA North Virginia
15 Le Way Drive
Branch No 723
Fredericksburg, VA 22406
(540) 373-7800/(540) 371-4123
WHOLESALE ASSESSMENT ONLY

Make/Model:	**2016 FORD F-250**
Bodystyle/Series:	**Regular Cab XL**
Color:	**White**
Mileage:	**65,844 (Verified)**
Turn-in Mileage:	-
VIN:	**1FDBF2B62GEC46531**
Work Order/ Stock Number:	**46502819**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G630095S**
Vehicle Grade :	**Grade 1.5**
Remarks:	-
Announcements:	• Corrosion
Certification :	-
Req. Prev. Repair Order:	-



Drivable: Yes

Equipment

Transmission:	**Automatic Transmission**	A/C:	**Yes**
Engine:	**8-Cylinder Gas**	Cruise Control:	**Yes**
Engine Size:	**6.2 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**Yes**
Radio:	**AM Radio**	Pwr Windows	**Yes**
Interior - Type/Color:	**Cloth Interior /GRAY**	Rear Defroster:	**Yes**
Airbag:	**Driver Side Air Bag**	Tilt Steering:	**Yes**
Seats:	**Buckets**	Drive Type:	**4-Wheel Drive**
Seat Count:	-	Brakes:	**Disc**

Equipment

Additional Equipment:

Car Tire Size - LF 245 / 75 R 17	Car Tire Size - LR 245 / 75 R 17	Car Tire Size - RR 245 / 75 R 17
Car Tire Size - RF 245 / 75 R 17	LF Tires - 12/32 inch	LR Tires - 11/32 inch
RF Tires - 12/32 inch	RR Tires - 11/32 inch	Tire Brand - Front Left - FALKEN
Tire Brand - Front Right - FALKEN	Tire Brand - Rear Left - FALKEN	Tire Brand - Rear Right - FALKEN
Tire Model - RR - Rubitrek A/T	Tire Model - RF - Rubitrek A/T	Tire Model - LR - Rubitrek A/T
Tire Model - LF - Rubitrek A/T		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Pickup Bed	Aftermarket	-	Acceptable
	Left Rear Rail	Previous Repair	-	Acceptable
	Right Rear Rail	Previous Repair	-	Acceptable

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Warning - Tire Pressure	On	-	Unacceptable
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 5	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Inside Bed	Multiple Scratches Heavy	-	10 Or More

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Bed Side	Multiple Scratches Heavy	-	3
	Left Front Fender	Heavy Scratch	-	1 To 2 Inches
	Left Front Wheel	Corrosion	-	4 To 5 Inches
	Roof	Chipped	-	2
	Front Metal Bumper Painted	Multiple Dents/Paint Damage	-	3
	Grille	Bug Damage	-	Repair Required

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Front Door	Multiple Scratches Heavy	-	4
	Right Front Wheel	Corrosion	-	1 To 2 Inches
	Right Bed Side	Multiple Scratches Heavy	-	6
	Right Rear Wheel	Corrosion	-	2 To 3 Inches
	Left Front Door	Multiple Scratches Heavy	-	2
	Rear Metal Bumper Painted	Dent(S) W/ Paint Dmg	-	> 12 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Tailgate	Multiple Scratches Heavy	-	10 Or More
	Exterior Rear Body Panel	Multiple Scratches Heavy	-	3

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.