Approved CR

IAA East Bay
2780 Willow Pass Road
Branch No 332
Bay Point, CA 94565
(925) 458-7610/(925) 458-7615
WHOLESALE ASSESSMENT ONLY



Make/Model:	**2018 RAM 1500**
	-
Bodystyle/Series:	**TRADESMAN 4X2 6`4 BOX**
Color:	**Silver**
Mileage:	**21,599 (Verified)**
Turn-in Mileage:	-
VIN:	**1C6RR6FG5JS283920**
Work Order/ Stock Number:	**46440302**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G42-0544V**
Vehicle Grade :	**Grade 3.3**
Remarks:	-
Announcements:	-
Certification :	-
Req. Prev. Repair Order:	-

Drivable: Yes

Equipment

Transmission:	**Automatic Transmission**	A/C:	**No**
Engine:	**6-Cylinder Flex Fuel**	Cruise Control:	**Yes**
Engine Size:	**3.6 L**	Pwr Steering:	**Yes**
Roof:	**Coach**	Pwr Locks:	**Yes**
Radio:	-	Pwr Windows	**Yes**
Interior - Type/Color:	**Cloth Interior /GRAY**	Rear Defroster:	**No**
Airbag:	**Driver Side Air Bag**	Tilt Steering:	**Yes**
Seats:	**3rd**	Drive Type:	**Rear Wheel Drive**
Seat Count:	-	Brakes:	**Disc**

Equipment

Additional Equipment:

Car Tire Size - RR 265 / 70 R 17	Car Tire Size - LF 265 / 70 R 17	Car Tire Size - RF 265 / 70 R 17
Car Tire Size - LR 265 / 70 R 17	LF Tires - 8/32 inch	LR Tires - 6/32 inch
RF Tires - 5/32 inch	RR Tires - 6/32 inch	Tire Brand - Front Left - ARGUS ADVANTA
Tire Brand - Front Right - ARGUS ADVANTA	Tire Brand - Rear Left - ARGUS ADVANTA	Tire Brand - Rear Right - ARGUS ADVANTA
Tire Model - RR - SVT-01	Tire Model - RF - SVT-01	Tire Model - LR - SVT-01
Tire Model - LF - SVT-01		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Running Board	Aftermarket	-	Acceptable
	Left Running Board	Aftermarket	-	Acceptable
	Warning Light - Engine	On	-	Unacceptable
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Front Metal Bumper Painted	Multiple Scratches Heavy	-	3
	Right Front Wheel	Corrosion	-	1/2 To 1 Inch
	Right Bed Side	Chipped	-	2

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Rear Wheel	Corrosion	-	1 To 2 Inches
	Tailgate	Chipped	-	2
	Left Front Wheel	Corrosion	-	2 To 3 Inches
	Left Front Door	Multiple Scratches Heavy	-	2
	Left Rear Door	Heavy Scratch	-	1 To 2 Inches

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.