



Approved CR

IAA El Paso
14751 Marina Ave
Branch No 420
El Paso, TX 79938
(915)852-2489/(915)852-2235
WHOLESALE ASSESSMENT ONLY

Make/Model: **2016 FORD F-450 CHASSIS**
Bodystyle/Series: **Regular Cab XLT**
Color: **White**
Mileage: **24,932 (Verified)**
Turn-in Mileage: **-**
VIN: **1FDUF4GT4GEB44800**
Work Order/
Stock Number: **46251991**
Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**
Client Stock #: **G31A0072**
Vehicle Grade : **Grade 4.0**
Remarks: **-**
Announcements: **-**
Certification : **-**
Req. Prev. Repair **-**
Order:



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	8-Cylinder Diesel	Cruise Control:	Yes
Engine Size:	6.7 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Leather/Cloth Interior /GRAY	Rear Defroster:	No
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Buckets	Drive Type:	Rear Wheel Drive
Seat Count:	-	Brakes:	Hydraulic Brakes

Equipment


Additional Equipment:

Car Tire Size - LR 225 / 70 R 19	Car Tire Size - LF 225 / 70 R 19	Car Tire Size - RF 225 / 70 R 19
Car Tire Size - RR 225 / 70 R 19	LF Tires - 11/32 inch	LR Tires - 11/32 inch
RF Tires - 11/32 inch	RR Tires - 11/32 inch	Tire Brand - Front Left - HANKOOK
Tire Brand - Front Right - HANKOOK	Tire Brand - Rear Left - HANKOOK	Tire Brand - Rear Right - HANKOOK
Tire Model - LF - Smart Flex AH35	Tire Model - LR - Smart Flex AH35	Tire Model - RF - Smart Flex AH35
Tire Model - RR - Smart Flex AH35		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
[no photo]	Personally Identifiable Info	De-Identify	-	-
	Rear Bumper	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Instrument Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Keys	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Engine	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Odometer	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
-------	------	--------	--------	----------

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Right Front Wheel	Bent	-	Replacement Required
	Overall Vehicle	De-Identify	-	Removal Required

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.